



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLW 4541R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	REPLACED	\$2,333.75	\$2,333.75
2	FRONT BUMPER BRACKET @ \$90.97	REPLACED	\$181.94	\$181.94
2	FRONT BUMPER SIDE RETAINER @\$111.33	REPLACED	\$222.66	\$222.66
1	FRONT BUMPER FOG LAMP COVER (GRAZED)	NOT CONSISTENT WITH THE IMPACT	\$199.79	\$0.00
1	FRONT BUMPER NOZZLE COVER (GRAZED)	NOT CONSISTENT WITH THE IMPACT	\$111.85	\$0.00
1	FRONT BUMPER NOZZLE PUMP (BENT)	NOT CONSISTENT WITH THE IMPACT	\$233.61	\$0.00
1	HEADLAMP RH	REPLACED	\$6,888.74	\$6,888.74
1	HEADLAMP BALLAST RH (FAULTY)	NOT CONSISTENT WITH THE IMPACT	\$933.81	\$0.00
1	HEADLAMP FULL LED DRL MODULE (RIGHT) (FAULTY)	NOT CONSISTENT WITH THE IMPACT	\$1,111.50	\$0.00
1	FRONT GRILLE COMPLETE (CRACKED)	NOT CONSISTENT WITH THE IMPACT	\$1,478.78	\$0.00
1	FRONT DOOR INNER GARNISH RH	REPLACED	\$999.79	\$999.79
1	FRONT FENDER RH	REPLACED	\$1,477.77	\$1,477.77
1	FRONT FENDER INNER SHIELD RH	REPLACED	\$233.34	\$233.34
1	FRONT FENDER SPONGE RH (CUT)	NOT CONSISTENT WITH THE IMPACT	\$147.74	\$0.00
1	FRONT KNUCKLE ARM RH	REPLACED	\$1,115.54	\$1,115.54
1	FRONT KNUCKLE ARM BEARING RH	REPLACED	\$777.41	\$777.41
1	FRONT KNUCKLE ARM BALL JOINT RH (BENT)	NOT CONSISTENT WITH THE IMPACT	\$200.41	\$0.00
1	FRONT LOWER ARM RH	REPLACED	\$577.44	\$577.44
1	FRONT SHOCK ABSORBER RH	REPLACED	\$777.58	\$777.58
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$1,558.60)
			\$20,003.45	\$14,027.36

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR RH (LOCAL REPAIR) (SN)	REPLACED	\$2,566.75	\$250.00
1	SET FRONT BUMPER CLIP (SN)	REPLACED	\$50.00	\$50.00
1	SET FRONT GRILLE CLIP (SN)	NOT NECESSARY	\$40.00	\$0.00
1	SET FRONT DOOR INNER TRIM BOARD CLIP RH (SN)	NOT NECESSARY	\$34.00	\$0.00
1	SET FRONT FENDER INNER SHIELD CLIP RH (SN)	REPLACED	\$32.00	\$32.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT SPORT RIM RH (LOCAL REPAIR) (SN)	REPLACED	\$1,555.75	\$250.00
			\$4,278.50	\$582.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGE TO REMOVE-REFIT, PANEL BEAT, STRAIGHTEN, RE-ALIGN AND REPAIR OF FRONT BUMPER, HEADLAMP RH, FRONT DOOR RH, FRONT FENDER RH AND OTHERS RELEVANT ACCIDENT DAMAGES	NOT NECESSARY	\$1,400.00	\$1,200.00
	TO REMOVE-REFIT FRONT RH UNDER CARRIAGE DAMAGE PARTS		\$300.00	\$200.00
	TO CONDUCT COMPUTERISE FRONT WHEEL ALIGNMENT TEST		\$80.00	\$60.00
	TO CHECK WIRINGS AND LIGHTINGS		\$50.00	\$30.00
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENT TO AFFECTED PANELS		\$150.00	\$30.00
	TOWING CHARGES		\$80.00	\$60.00
	TO TRANSFER FRONT RH DOOR FITTINGS AND ATTACHMENTS		\$120.00	\$0.00
	TO PUTTY AND SPRAY PAINTING CHARGES		\$1,200.00	\$660.00
			\$3,380.00	\$2,240.00
GRAND TOTAL			\$27,661.95	\$16,849.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$13,450.00
Report Ref No: CS/LAW24100238/Knh3m4				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.