

ASSIGNMENT

From: _____ Date: _____
 Entry Sheet
 (C) / TP RES / OD RES / EVA / INV / MV
 To In _____ Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client Record)
 Make of V: _____

Veh No: GBD912Z Yr Regr: 2014 / June
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Dyna CC: 2982
 Colour: Silver A/C: Insured / Std / Nil / N/A
 Sp. Reading: 461774 T/Radio: Insured / Std / Nil / N/A
 Eng/No: _____
 C/No: JTFAT35Y90K203024
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15C
 R: 155R12C

(Policy Condition)
 Remark: Trench had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Min. Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXH / OVA / GY / FS / LIZA / WIC / OHTSU / PIR / SUMI /
 TOYO / OKO or

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 05/05/25
 Survey held at Modern
 Des. of Damages: Frt / Rear / O/S / W/S / U/C / Rooftop or
Front N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP China</u>
	COE Expiry: <u>04/06/2029</u>
	Estimate given during: Yes () 1st Survey: No ()
	MV: <u>42K</u>
	PV: <u>28.91K</u>
	Nett: <u>13.11K</u>
	<u>043D</u>

Date/Tm, File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Survey Fee: _____
 Transportation: _____
 Photos: _____
 Others: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)

Report Forward: _____
 E-mail: _____

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Quotation

DATE : 27.11.2024
 VEH NO : GBD912Z
 MODEL : Toyota Dyna
 D O A : 11.10.2024
 YR REF : XE976Z

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBD912Z (TOYOTA DYNA)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Panel <i>Dented</i>	1	1,281.90 ✓
2	Front Panel Dyna Wording <i>new</i>	1	89.90 ✓
3	Front Grille <i>new</i>	1	622.90 +
4	Front Grille Logo <i>new</i>	1	71.20 +
5	Head Lamp - LH <i>new</i>	1	1,105.90 +
6	Front Corner Panel - LH <i>new</i>	1	388.50 +
7	Front Panel Top Moulding - Centre <i>could</i>	1	412.40 ✓
8	Front Panel Top Moulding - LH <i>could</i>	1	144.20 ✓
9	Wiper Panel Garnish <i>Dented</i>	1	476.20 ✓
10	Front Wing Mirror - Rectangular <i>new</i>	1	185.30 +
11	Front Wing Mirror - Round <i>new</i>	1	98.90 +
12	Front Wing Mirror Stay Cover <i>could</i>	1	176.50 ✓
13	Front Windscreen Glass <i>could</i>	1	1,322.40 ✓
14	Front Windscreen Glass Moulding <i>new</i>	1	327.60 ✓
15	Tailgate Lock Cover <i>new</i>	1	55.90 +
16	Front Bumper <i>new</i>	1	621.60 +
17	Front Bumper Bracket <i>new</i>	1	219.10 +
18	Air Con Blower <i>new</i>	1	1,845.90 +
19	Air Con Cooling Coil <i>new</i>	1	1,338.70 +
<i>Front Wing Mirror Stay 295 ✓</i>			
<i>Best</i>			
Less 25%			
			\$ 10,785.00
			\$ (2,696.25)
			\$ 8,088.75

S/NETT ITEMS

1	Front Panel Sealant <i>new</i>	1 set	60.00 ✓
2	Front Grille Clips <i>new</i>	1 set	30.00 ✓
3	Front Panel Top Moulding Centre Clips <i>new</i>	1 set	30.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR GBD912Z (TOYOTA DYNA)

4	Front Panel Top Moulding LH Clips <i>neu</i>	1 set	20.00 ✓
5	Wiper Panel Garnish Clips <i>neu</i>	1 set	30.00 ✓
6	Front Wing Mirror Stay Cover Clips <i>neu</i>	1 set	20.00 ✓
7	Front Windcreens Sealant <i>neu</i>	1 set	60.00 ✓
8	ERP Bracket <i>neu</i>	1	30.00 ✓

280.00

Total parts

\$ 8,368.75

LABOUR CHARGE

1	To knocking out front portion & renew above parts	\$ 1,200.00 <i>500</i>
2	To putty & spray up paint works	\$ 1,200.00 <i>600</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To apply tuff coat	\$ 150.00 <i>60</i>
5	To remove front windscreen glass	\$ 180.00 <i>120</i>
6	To remove dashboard	\$ 350.00 <i>+</i>
7	To remove aircon system	\$ 380.00 <i>+</i>

Total Labour

\$ 3,510.00

Grand Total

\$ 11,878.75

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Addition King
2/s 05/05/15
05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: