

SND 2874 U

Head lamp assy LH	Cur/mgum	\$2180.40 ✓
Rt bumper assy	cm	\$134.00 ✓
lower bracket LH	Bul/nd	\$871.20 ✓
reinforcement	n	\$386.90 X
retainer LH	cm	\$46.00 ✓
lower grille	ln	\$246.20 X
fender LH	n	\$580.40 X
outer garnish LH	Cur	\$264.20 ✓
inner shield LH	ln	\$120.80 X

208

To remove & refit damaged affected parts	\$600.00	300h
To Spray paint on affected areas	\$600.00	400h
To align headlamp and check wiring	\$40.00	20h
Tuft coat on affected areas	nn \$60.00	X

Not Authorised
Primary B4 paint

3 days \$3516.64

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: