

03/C12 24100242/K9h3

ASS. REC. BY:

REF:

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8112k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

1/ EH not ready

16/10 83516.64 Cash Used @ 1647.64, 32%

Veh No: SND 2874U Yr Regn: 12, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.G. 1498

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading: 59170 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RV3 1003143

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm R/Bal. 3 mm

L/Bal. 2 mm L/Bal. 3 mm

D.O.A. 10/10/24 D.O.I. 15/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Fr

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prell. Report

1) 18/10 10:00

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS. SI

), Extras

), Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Report Format :

E2 claims - TP

Lump Sum N.B.I: (\$

3516.64

SND 2874 U

Head lamp assy LH	Cur/mbrm	\$ 2180.40 ✓
1 1/2" bumper ^{lower} bracket LH	cm	\$ 134.00 ✓
" " reinforcement	Bul/nd	\$ 871.20 ✓
" " retainer LH	R	\$ 386.90 X
" " lower grille	cm	\$ 46.00 ✓
" fender LH	In	\$ 246.20 X
" " outer garnish LH	R	\$ 580.40 X
" " inner shield LH	Cur	\$ 264.20 ✓
	Sn	\$ 120.80 X

208

To remove & refit damaged affected parts	\$ 600.00	300h
To Spray paint on affected areas	\$ 600.00	400h
To align headlamp and check wiring	\$ 40.00	20h
Tuft coat on affected areas	NN \$ 60.00	X

Not Authorized
Performing B4 paint

3 days \$ 3516.64

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: