



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SDT 8080M

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DISTORTED	\$890.80	\$890.80
1	FRONT BUMPER FOGLAMP OUTER GARNISH WITH CHROME	CRACKED	\$158.40	\$158.40
1	FRONT BUMPER LH DAYLIGHT	CRACKED	\$496.60	\$496.60
1	FRONT BUMPER LH FOGLAMP	CRACKED	\$361.90	\$361.90
2	FRONT BUMPER LH PARKING SENSOR @\$258.20	DAMAGED (1PC ONLY)	\$516.40	\$258.20
2	FRONT BUMPER LH PARKING SENSOR 'O' RING @\$15.00	NECESSARY (1PC ONLY)	\$30.00	\$15.00
1	FRONT BUMPER LH REINFORCEMENT BRACKET	NOT NECESSARY	\$215.90	\$0.00
1	FRONT BUMPER LH SIDE RETAINER	NOT NECESSARY	\$47.30	\$0.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	\$407.80	\$0.00
4	FRONT BUMPER PARKING SENSOR HOLDER @\$53.20	NECESSARY	\$212.80	\$212.80
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$900.40	\$0.00
1	FRONT BUMPER SPONGE	CRACKED	\$315.20	\$315.20
1	FRONT BUMPER TOP SIDE BRACKET	NOT NECESSARY	\$108.60	\$0.00
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	\$29.30	\$0.00
1	FRONT GRILLE	CRACKED	\$606.80	\$606.80
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	\$88.80	\$88.80
1	FRONT LH HEADLAMP	CUT	\$3,628.00	\$3,105.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	\$954.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$996.90)	(\$650.95)
			<b>\$8,972.10</b>	<b>\$5,858.55</b>
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	FRONT BUMPER NUMBER PLATE (SN)	NOT NECESSARY	\$25.00	\$0.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	\$40.00	\$20.00
			<b>\$215.00</b>	<b>\$50.00</b>



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)	NOT NECESSARY	\$80.00	\$80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$800.00	\$200.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT		\$800.00	\$300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$80.00	\$0.00
			\$1,760.00	\$580.00
GRAND TOTAL			\$10,947.10	\$6,488.55
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$5,100.00
Report Ref No: CS/AGI24100244/Avp3e2				

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.