

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100245/EVP3E2
Date: 25/10/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLU5228A	Insured Vehicle No :	SMU6434C
Date of Loss:	08/10/2024	Nature of Claim:	TP
		Claim No:	DMPC2401360H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU5228A	Engine No:	HRA2531244A
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT (A)	Chassis No:	SJNFEAJ11U2121651
Reg. Date:	05/12/2017 (Man. Year: 2017)	Odometer:	91547 km
Colour:	White		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,925.00	1,529.00	11,396.00	88.17
Miscellaneous Items	200.00	100.00	100.00	50.00
Labour	3,180.00	1,130.00	2,050.00	64.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,305.00	2,759.00	13,546.00	83.08
+ GST 9.00/9.00% (S\$)	1,467.45	248.31	1,219.14	83.08
Nett Amount (S\$)	17,772.45	3,007.31	14,765.14	83.08

INSPECTION

Date of Assignment:	15/10/2024	Present Location:	Century Motors (Singapore) Pte Ltd (HQ)
Date Inspected:	15/10/2024	Inspected At:	Century Motors (Singapore) Pte Ltd (HQ) 6 Marsiling Lane, Singapore 739145
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2024)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU5228A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (WCP)	Repair	550.00 F	*- F
2	1		*FRT NUMBER PLATE GANISH (WCP)	Not Necessary	220.00 F	*- F
3	1		*HEADLAMP RH (WCP)	Not Necessary	2,400.00 F	*- F
4	1		*HEADLAMP LH (WCP)	Not Necessary	2,400.00 F	*- F
5	1		*FRT GRILLE TRIM(CHROME) (WCP)	Not Necessary	450.00 F	*- F
6	1		*REAR BUMPER (WCP) }	Dented	550.00 F	*550.00 F
7	1		*REAR BUMPER BRKT RH (WCP)	Not Necessary	110.00 F	*- F
8	1		*REAR BUMPER BRKT LH (WCP)	Not Necessary	110.00 F	*- F
9	1		*REAR BUMPER LOWER MOULDING (NPA) }	Not Necessary	-	*- F
10	1		*REFLECTOR RH (WCP)	Not Necessary	55.00 F	*- F
11	1		*REFLECTOR LH (WCP)	Not Necessary	55.00 F	*- F
12	1		*REAR REINFORCEMENT (WCP)	Dented	420.00 F	*420.00 F
13	1		*REAR END PANEL (WCP)	Repair	360.00 F	*- F
14	1		*TAILGATE (WCP)	Repair	2,400.00 F	*- F
15	1		*TAILGATE HINGE RH (WCP)	Not Necessary	50.00 F	*- F
16	1		*TAILGATE HINGE LH (WCP)	Not Necessary	50.00 F	*- F
17	1		*TAILLAMP RH (WCP)	Not Necessary	270.00 F	*- F
18	1		*TAILLAMP LH (WCP)	Not Necessary	270.00 F	*- F
19	1		*INNER TAILLAMP RH (WCP)	Not Necessary	250.00 F	*- F
20	1		*INNER TAILLAMP LH (WCP)	Not Necessary	250.00 F	*- F
21	1		*REAR NUMBER PLATE LIGHT RH (WCP)	Not Necessary	55.00 F	*- F
22	1		*REAR NUMBER PLATE LIGHT LH (WCP)	Not Necessary	55.00 F	*- F
23	1		*REAR PARKING SENSOR (WCP)	Broken	200.00 F	*200.00 F
24	1		*REAR WHEEL ARCH RH (NPA)	Not Necessary	-	*- F
25	1		*REAR WHEEL ARCH LH (NPA)	Not Necessary	-	*- F

Report was unsubmitted during this print-out.

10/25/24, 10:19 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Supplementary #1						
26	1		*REAR REINFORCEMENT BRKT LH (WCP)	Bent	110.00 F	*110.00 F
27	1		*REAR REINFORCEMENT BRKT RH (WCP)	Bent	110.00 F	*110.00 F
F=Franchise part.						
Sub Total (S\$)					11,750.00	1,390.00
+ Margin on L,N Items 10.00/10.00% (S\$)					1,175.00	139.00
Total Parts (S\$)					12,925.00	1,529.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT BUMPER CLIPS (NECESSARY)	30.00	30.00
2	1	FRT NUMBER PLATE AND HOLDER (CUT)	40.00	40.00
3	1	REAR BUMPER CLIPS (NECESSARY)	30.00	30.00
4	1	REAR NUMBER PLATE AND HOLDER (NOT NECESSARY)	40.00	0.00
5	1	REAR WINDSCREEN SEALANT (NOT NECESSARY)	60.00	0.00
Sub Total (\$\$)			200.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	1,680.00	500.00
2	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	1,200.00	600.00
3	TO VACUUM, WAXING & CLEAN INC SUNDRIES	New	150.00	30.00
4	LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	0.00
Gross Labour Cost (\$\$)			3,180.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >