

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24060214/UMA3Q2**Date:** 18/10/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210075460
Claimant Vehicle No : SNK7767B **Insured Vehicle No :** SJY5573E
Date of Loss: 21/06/2024 Nature of Claim: TP Claim No: 4723816255SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNK7767B**
Make & Model: TOYOTA LEXUS, 2.5 ES300H 4DR SEDAN (AUTO) EXECUTIVE (A) Engine No: A25A3A76865
Reg. Date: 12/05/2023 (Man. Year: 2023) Chassis No: JTHB21B1702202996
Colour: Silver Odometer: 7903 km
Engine Capacity: 2487 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18
Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,374.50	5,261.31	7,113.19	57.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	1,300.00	1,920.00	59.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,594.50	6,561.31	9,033.19	57.93
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	15,594.50	5,200.00	10,394.50	66.65
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 03/07/2024
Date Inspected: 03/07/2024 Inspected At: Specialists Motor Pte Ltd (HQ)
Blk 3018A Ubi Road 1, #01-24/25/26
Singapore 408711
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Dented	2,416.50 F	*2,000.80 FL
2	1		*FRONT FENDER COWLING RH	Serviceable	717.00 F	*- FL
3	1		*SET FRONT FENDER COWLING CLIPS RH	Not Necessary	55.00 F	*- FL
4	1		*FRONT DOOR ASSY RH	Dented / Bent	3,043.00 F	*3,043.00 FL
5	1		*FRONT DOOR W/STRIP RH	Not Necessary	402.40 F	*- FL
6	1		*FRONT DOOR OUTER FRAME (TOP)	Not Necessary	351.70 F	*- FL
7	1		*FRONT DOOR OUTER FRAME (BOTTOM)	Not Necessary	329.80 F	*- FL
8	1		*FRONT WHEEL RIM RH	Serviceable	4,257.00 FS	*- FS
9	1		*FRONT SHOCK ABSORBER RH	Bent	802.10 F	*802.10 FL
					Sub Total (\$\$)	12,374.50
					- List Item Discount on L Items 0.00/10.00% (\$\$)	584.59
					Total Parts (\$\$)	5,261.31

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT RENEW ,KNOCKING & WELDING FRONT FENDER RH ,FRONT DOOR ASSY RH ,REMOVE & INSTALL ALL DAMAGE PARTS & REALIGN BODY	New	1,080.00	400.00
2	REMOVE & INSTALL FRONT DOOR LOCK GLASS & ETC	New	180.00	50.00
3	TUFF KOTE ON DAMAGE PARTS	New	80.00	30.00
4	TO DISMANTLE & REPLACED FRONT UNDERCARRIAGE	New	380.00	120.00
5	COMPUTERIZED WHEEL ALIGNMENT	New	180.00	80.00
6	SPRAY PAINTING ON DAMAGE PARTS	New	1,280.00	600.00
7	CHECK ALL LIGHTING AFTER REPAIRS	New	40.00	20.00
Gross Labour Cost (\$\$)			3,220.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >