



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2501399

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 11/03/2025
Reference CD/CTI24100248/Kma3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKE 1661D
Insured Veh. GBJ 1900U
Claim No. SNM24D205798
Policy No. DMCVSNW00004332403
Accident Date 12/10/2024
Inspection Date 15/10/2024

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (9%) | 36.00 |
| Grand Total | 436.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|--|-------------------------------|----------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CD/CTI24100248/Kma3q2(N) | |
| | | | Date: 11/03/2025 | |
| | | | Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBJ 1900U | Veh. Inspected | SKE 1661D |
| | Policy No. | DMCVSNW00004332403 | Coverage (\$) | 0.00 |
| | Claim No. | SNM24D205798 | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 15/10/2024 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TESLA MODEL 3 (A) | c.c | 0 |
| | Engine No. | HIDDEN | Year of Reg. | 2020 |
| | Chassis No. | 5YJ3F7EA2LF572909 | Colour | METALLIC PEARL WHITE |
| | Odometer | 73257 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 235/45Z R18 | MICHELIN | 7 mm |
| | L/H Front Tyre | 235/45Z R18 | MICHELIN | 7 mm |
| | R/H Rear Tyre | 235/45Z R18 | MICHELIN | 7 mm |
| | L/H Rear Tyre | 235/45Z R18 | MICHELIN | 7 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 12/10/2024 | Inspection Date | 15/10/2024 |
| | Survey held at | OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 1661D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT BUMPER | MTG CRACKED | 766.00 | 766.00 |
| 1 | FRONT BUMPER LICENCE PLATE MOUNTING BRACKET | DENTED | 29.90 | 29.90 |
| 1 | FRONT BUMPER ENERGY ABSORBER | SERVICEABLE | 46.73 | - |
| 2 | FRONT PARKING SENSOR @\$163.55 | SERVICEABLE | 327.10 | - |
| 1 | SET FRONT PARKING SENSOR MOUNTING BRACKET | SERVICEABLE | 28.02 | - |
| | LESS 10% DISCOUNT | | -119.78 | -79.59 |
| | | | 1,077.97 | 716.31 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | FRONT BUMPER CLIPS (SN) | NECESSARY | 55.00 | 55.00 |
| 1 | FRONT BUMPER LOWER CLIPS (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | FRONT FENDER LINER CLIPS (SN) | NOT NECESSARY | 55.00 | - |
| 1 | FRONT LICENCE PLATE NUMBER WITH FRAME (SN) | CRACKED | 140.00 | 45.00 |
| | | | 300.00 | 150.00 |
| | <u>LABOUR</u> | | | |
| | LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. | | 400.00 | 200.00 |
| | LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ETC. | | 350.00 | 220.00 |
| | LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER REVERSE SENSOR & ETC. | | 100.00 | 60.00 |
| | TO CHECK WIRING AND ELECTRICAL SYSTEM. | NOT NECESSARY | 100.00 | - |
| | | | 950.00 | 480.00 |
| | GRAND TOTAL | | 2,327.97 | 1,346.31 |
| | RECOMMENDED COST OF REPAIRS | | | 1,346.31 |

Report Ref No. CD/CT124100248/Kma3q2(N)


KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SKE 1661D



PHOTOGRAPHS FOR VEHICLE NO. : SKE 1661D



PHOTOGRAPHS FOR VEHICLE NO. : SKE 1661D



PHOTOGRAPHS FOR VEHICLE NO. : SKE 1661D

