



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMX 2832Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LH FENDER	DENTED	\$2,952.50	\$749.00
1	FRONT LH FENDER 'HYBRID' EMBLEM	NECESSARY	\$88.80	\$88.80
1	FRONT LH FENDER ARCH GARNISH	DEFORMED	\$203.30	\$203.30
1	FRONT LH FENDER INNER SHIELD COVER	NOT NECESSARY	\$327.10	\$0.00
1	FRONT LH HEADLAMP	NOT NECESSARY	\$2,822.00	\$0.00
1	FRONT LH HEADLAMP LOWER PANEL	NOT NECESSARY	\$95.10	\$0.00
1	FRONT LH KNUCKLE ARM	DAMAGED	\$974.10	\$974.10
1	FRONT LH KNUCKLE ARM BEARING	DAMAGED	\$846.90	\$705.00
1	FRONT LH LOWER ARM	BENT	\$1,166.90	\$898.00
1	FRONT LH SHOCK ABSORBER	NOT NECESSARY	\$687.60	\$0.00
1	FRONT LH SIDE MIRROR ASSY	TO REPAIR SEE LABOUR	\$2,077.70	\$0.00
1	FRONT LH TIE ROD END	NOT NECESSARY	\$261.70	\$0.00
1	REAR BUMPER	NOT NECESSARY	\$545.80	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$3,262.38)	(\$904.55)
			\$9,787.12	\$2,713.65

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LH SPORT RIM (SN)	CUT	\$2,214.38	\$600.00
1	SET FRONT LH FENDER ARCH GARNISH CLIPS (SN)	NECESSARY	\$30.00	\$20.00
1	SET FRONT LH FENDER INNER SHIELD COVER CLIPS (SN)	NOT NECESSARY	\$30.00	\$0.00
1	FRONT LH TYRE (SN)	NOT NECESSARY	\$380.00	\$0.00
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
			\$2,704.38	\$620.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)		\$80.00	\$30.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION		\$260.00	\$200.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM		\$100.00	\$80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$1,600.00	\$700.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT LH SIDE MIRROR ASSY		\$1,400.00	\$400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$120.00	\$30.00
			\$3,560.00	\$1,440.00
<b>GRAND TOTAL</b>			<b>\$16,051.50</b>	<b>\$4,773.65</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>\$3,800.00</b>
Report Ref No: CS/INC24100254/Anh3e2				

TOTAL FOR SPARE PARTS: \$ 12,491.50 \$ 3,333.65  
TOTAL FOR LABOUR : \$ 3,560.00 \$ 1,440.00  
TOTAL REPAIR COST: \$ 16,051.50 \$ 4,773.65

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.