

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24060215/UVH3E2
Date: 24/07/2024REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG23014752
Claimant Vehicle No :	SMW8884M	Insured Vehicle No :	GBK7610L
Date of Loss:	21/06/2024	Nature of Claim:	TP
		Claim No:	CDMCG24001535

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW8884M		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM025260
Reg. Date:	13/10/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF5XMA000508
Colour:	Green	Odometer:	77639 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,340.22	5,664.51	1,675.71	22.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	650.00	1,580.00	70.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,570.22	6,314.51	3,255.71	34.02
Approved Total (Overridden) (\$\$)		5,000.00		
(\$\$)	9,570.22	5,000.00	4,570.22	47.75
+ GST 9.00/9.00% (\$\$)	861.32	450.00	411.32	47.75
Nett Amount (\$\$)	10,431.54	5,450.00	4,981.54	47.75

INSPECTION

Date of Assignment:	24/06/2024		
Date Inspected:	25/06/2024	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2024)
Parts:	143	AUDI A5 2.0 SPORTBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW8884M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR O/S	Badly Dented	4,200.00 FN	*3,990.00 FN
2	1		*REAR DOOR HINGE O/S	Serviceable	110.00 FN	*- FN
3	1		*REAR DOOR CHECKER O/S	Twisted	121.00 FN	*121.00 FN
4	1		*REAR DOOR GLASS REGULATOR O/S	Damaged	398.00 FN	*398.00 FN
5	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed / Cracked	1,616.05 FN	*1,616.05 FN
6	1		*REAR DOOR INNER RUBBER O/S	Necessary	168.85 FN	*168.85 FN
7	1		*REAR DOOR INNER LOCK O/S	Serviceable	443.75 FN	*- FN
8	1		*REAR DOOR OUTER MOULDING O/S	Not Necessary	199.15 FN	*- FN
9	1		*CENTRE PILLAR O/S	Repair	899.00 FN	*- FN
						F=Franchise part. N=NettItemDisc.
					Sub Total (\$\$)	8,155.80 6,293.90
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	815.58 629.39
					Total Parts (\$\$)	7,340.22 5,664.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	100.00	30.00
3	TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM }	New	580.00	100.00
4	TO TRANSFER REAR DOOR MECHANISM }	New	100.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	200.00
6	TO PUTTY & SPRAY PAINTING	New	800.00	300.00
Gross Labour Cost (\$)			2,230.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >