

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100257/KNP3E2**Date:** 04/11/2024REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No :

SMK1312G

Insured Vehicle No :

SMA2424M

Date of Loss: 30/09/2024

Nature of Claim:

TP

Claim No:

DMPC2401323H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMK1312G

Make & Model:

MERCEDES-BENZ GLB200, 1.3 PROGRESSIVE (A)

Engine No:

28291480389871

Reg. Date:

16/02/2021 (Man. Year: 2020)

Chassis No:

W1N2476872W072562

Colour:

White

Odometer:

95163 km

Engine Capacity:

1332 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$):

Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

235/55 R18

Rear Tyre Size:

235/55 R18

Front Left Side:

Bridgestone 9 mm

Rear Left Side:

Bridgestone 9 mm

Front Right Side:

Bridgestone 9 mm

Rear Right Side:

Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,798.10	5,259.90	5,538.20	51.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,095.00	1,855.00	62.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,748.10	6,354.90	7,393.20	53.78
+ GST 9.00/9.00% (\$\$)	1,237.33	571.94	665.39	53.78
Nett Amount (\$\$)	14,985.43	6,926.84	8,058.59	53.78

INSPECTION

Date of Assignment:

15/10/2024

Date Inspected:

15/10/2024

Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2024)
Parts:	M1-SUV	MERCEDES-BENZ GLB200 1.3 PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK1312G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,295.00 FN	*2,295.00 FN
2	1		*TAILGATE GLB200 EMBLEM	Necessary	103.00 FN	*103.00 FN
3	1		*TAILGATE CENTER LOGO	Necessary	65.00 FN	*65.00 FN
4	1		*REAR END PANEL	Repair	3,118.00 FN	*- FN
5	1		*REAR BUMPER	Cracked	1,555.00 FN	*1,555.00 FN
6	1		*REAR BUMPER REINFORCEMENT	Repair	770.00 FN	*- FN
7	1		*REAR BUMPER CENTER INNER FRAME	Serviceable	150.00 FN	*- FN
8	1		*REAR BUMPER TOP CHROME	Necessary	270.00 FN	*270.00 FN
9	1		*REAR BUMPER LOWER GARNISH	Dented / Cut	283.00 FN	*283.00 FN
10	1		*REAR BUMPER LOWER CHROME	Serviceable	1,578.00 FN	*- FN
11	2		*REAR BUMPER SENSOR	Serviceable	432.00 FN	*- FN
12	6		*REAR BUMPER SENSOR SEALS	Necessary	72.00 FN	*72.00 FN
13	15		*REAR BUMPER CLIPS	Necessary	135.00 FS	*60.00 FS
14	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
15	1		*TAILGATE C&C EMBLEM	Necessary	38.00 FS	*38.00 FS
16	1		*TAILLAMP ASSY - RH	Mtg Cracked	458.00 FN	*458.00 FN
17	1		*TAILLAMP LOWER BRACKET - RH	Cracked	590.00 FN	*590.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	11,972.00	5,829.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,173.90	569.10
Total Parts (\$\$)	10,798.10	5,259.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
2	TO TRANSFER DAMAGED TAILGATE INTERIOR PARTS TO NEW TAILGATE	New	120.00	60.00
3	TO REMOVE & REFIT REAR BUMPER SENSOR	New	100.00	60.00
4	TO CHECK & RECTIFY WIRING SYSTEM	New	80.00	15.00
5	TO REMOVE & REFIX REAR INTERIOR GARNISHES & TRIMBOARD TO FACILITATE THE REPAIRS	New	180.00	0.00
6	TO PUTTY & SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	440.00
7	TO APPLY RUST-PROOFING ON REPLACED & REPAIRED PANELS	New	120.00	0.00
8	TO PANEL BEAT AND STRAIGHTEN REAR CHASSIS FRAME, REAR FLOORBOARD PANEL, TO CUT & WELD REAR END PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT & ADJUST THE SAME	New	1,200.00	400.00
Gross Labour Cost (\$)			2,950.00	1,095.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >