



HxGN EAM

Accident Report

User

VELMURUGANS@SBSTRANSIT.COM.SG

Report Created

Oct 22, 2024

Certificate of Bus Repair

Depot	SE	Bus No	SBS6568R
Driver	88086	Accident Date	Oct 10, 2024
Work Order No	1562474	Case No / AR No	23264 / AR-2024-5567

Date IN Oct 10, 2024

Date Out

Oct 21, 2024

Registration Date	Model/Manufacturer	Chassis No.
Jun 2, 2015	MB Citaro O530, SD, AC, 2 Axle	WEB62808323128603

Stock Code	Description	Quantity	Total Material Cost (S\$)
30600032 N	LED LICENSE PLATE LAMP;RR N	1	\$48.73
30600438 N	RUBBER BUMPER.RR END.20.6X20.6X7.6 N	4	\$3.32
30600414 N	BRACKET;REAR PANEL N	1	\$11.80
30600209 N	FLAP LESS LOCK;RR END N	1	\$2,658.57
90082461 N	STKR SBS TRANSIT REAR.SG BUS N	1	\$7.20
90082468 N	STKR SG "LOVE" LOGO.REAR N	1	\$9.99
30600743 N	BUMPER CENTRE.REAR BUMPER COMPL N	1	\$933.91
30600106 N	CROSSMEMBER N	1	\$1,245.00
90082256 N	STKR 60KM/H N	1	\$0.93

TOTAL FOR PARTS		S\$	4,919.45
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	Workshop Labour	S\$	188.00
2	Contractor's Repair Charges	S\$	2,000.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST		S\$	2,188.00
Repair cost of Advertisement / Livery		S\$	0.00
TOTAL DAMAGE		S\$	7,107.45
Overheads		S\$	2,132.24

EAM

Accident Report



	Towing Charges	S\$	0.00
Repair Period : 4.00 Days	Loss of Use	S\$	1,632.40
	TOTAL LOSS	S\$	10,872.09