



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SBS 6568R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	LED LICENSE PLATE LAMP;RR N	DENTED	\$48.73	\$48.73
4	RUBBER BUMPER.RR END.20.6X20.6X7.6 N	NECESSARY	\$3.32	\$3.32
1	BRACKET;REAR PANEL N	DISTORTED	\$11.80	\$11.80
1	FLAP LESS LOCK;RR END N	BENT	\$2,658.57	\$2,658.57
1	STKR SBS TRANSIT REAR.SG BUS N	NECESSARY	\$7.20	\$7.20
1	STKR SG "LOVE" LOGO.REAR N	NECESSARY	\$9.99	\$9.99
1	BUMPER CENTRE.REAR BUMPER COMPL N	BENT	\$933.91	\$933.91
1	CROSSMEMBER N	BENT	\$1,245.00	\$1,245.00
1	STKR 60KM/H N	NECESSARY	\$0.93	\$0.93
			\$4,919.45	\$4,919.45

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	WORKSHOP LABOUR		\$188.00	\$188.00
	CONTRACTOR'S REPAIR CHARGES		\$2,000.00	\$2,000.00
			\$2,188.00	\$2,188.00

GRAND TOTAL		\$7,107.45	\$7,107.45
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)		\$7,107.45
Report Ref No: CS/LPC24100258/Kvh3e2			

**KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.