

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL INSURANCE LTD		Ref:	CS/FCI24100259/Anp3e2	
	16 RAFFLES QUAY		Date:	19/11/2024	
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2	
_	SINGAPORE 04030				
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 4711E	Veh. Inspected	SLK 8213A	
	Policy No.	-	Coverage	0	
	Claim No.	D24009024MFCT	Excess	\$0.00	
	Assign From	HARMINDER	Assign Date	15/10/2024	
2.	2. Vehicle Details				
	Make & Model	MAZDA 3	C.C	1496	
	Engine No.	P520424589	Year of Reg.	27/01/2017	
	Chassis No.	JM6BN22A8H0138224	Colour	BLUE	
	Odometer	158656 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/45 R17	MICHELIN	6	
	L/H Front Tyre	225/45 R17	MICHELIN	6	
	R/H Rear Tyre	225/45 R17	MICHELIN	6	
	L/H Rear Tyre	225/45 R17	MICHELIN	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	11/10/2024	Inspection Date	14/10/2024	
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	Sa. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair