



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMH 1632Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOOT LID	TO REPAIR SEE LABOUR	\$955.60	\$0.00
1	REAR BOOT LID - LOGO	NECESSARY	\$55.10	\$55.10
1	REAR BOOT LID EMBLEM - ALTIS	NECESSARY	\$65.70	\$65.70
1	REAR BOOT LID EMBLEM - COROLLA	NECESSARY	\$75.10	\$75.10
2	REAR BOOT LID LAMP @\$655.70	SERVICEABLE	\$1,311.40	\$0.00
1	REAR BOOT RUBBER	SERVICEABLE	\$205.60	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$685.70	\$0.00
1	REAR END PANEL INNER GARNISH	DENTED	\$263.70	\$168.20
1	REAR N/S FENDER INNER TRIM	DEFORMED/CRACKED	\$487.50	\$487.50
1	REAR N/S FENDER	TO REPAIR SEE LABOUR	\$1,015.70	\$0.00
1	REAR N/S FENDER AIR DUCT	SERVICEABLE	\$155.70	\$0.00
2	REAR TAIL-LAMP ASSY @\$750.60	MTG CRACKED	\$1,501.20	\$1,413.20
1	REAR BUMPER	BUCKLED	\$687.60	\$687.60
1	REAR BUMPER REINFORCEMENT	BENT	\$455.10	\$455.10
2	REAR BUMPER SIDE RETAINER @\$95.10	DISTORTED	\$190.20	\$190.20
2	REAR N/S BUMPER REFLECTOR @\$105.10	SERVICEABLE	\$210.20	\$0.00
	LESS 25.00% DISCOUNT		(\$2,080.28)	(\$899.43)
			\$6,240.82	\$2,698.27

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR REVERSE SENSOR (SN)	CUT/DENTED	\$296.33	\$200.00
20	CLIP @\$2.00 (SN)	NECESSARY	\$40.00	\$40.00
			\$336.33	\$240.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR BOOT LID, REAR END PANEL AND REAR N/S FENDER		\$1,200.00	\$400.00
	TO PUTTY & SPRAY PAINT REAR ACCIDENT AFFECTED PORTION		\$1,200.00	\$600.00
	CHECK/RECONNECT WIRING		\$45.00	\$20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	NOT NECESSARY	\$180.00	\$0.00
			\$2,625.00	\$1,020.00
GRAND TOTAL			\$9,202.15	\$3,958.27
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,100.00
Report Ref No: CS/SMO24100260/Knp3m4				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.