

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24060216/UMA3Q2
Date: 03/09/2024

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900067101
Claimant Vehicle No :	SKX4873P	Insured Vehicle No :	SMJ6132G
Date of Loss:	21/06/2024	Nature of Claim:	TP
		Claim No:	4442469784SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX4873P	Engine No:	2ZR1669190
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W50J003139
Reg. Date:	16/12/2015 (Man. Year: 2015)	Odometer:	183134 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,445.47	8,289.27	5,156.20	38.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,980.00	1,720.00	36.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,145.47	11,269.27	6,876.20	37.89
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	18,145.47	9,000.00	9,145.47	50.40
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
Nett Liability (S\$)		9,720.00		
Global Sum Settlement (S\$)		9,720.00		

INSPECTION

Date of Assignment:	26/06/2024	Leang Automotive (HQ)
Date Inspected:	26/06/2024 Inspected At:	1 KAKI BUKIT AVE 6, #01-68 AUTOBAY@KAKI BUKIT
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,288.10 FL	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	145.40 FL	*145.40 FL
3	1		*TAILGATE	Badly Dented	1,842.00 FL	*1,842.00 FL
4	1		*TAILGATE OUTER HANDLE	Cracked	299.40 FL	*299.40 FL
5	2		*TAILGATE REFLECTORS	Serviceable	364.80 FL	*- FL
6	1		*TAILGATE REAR LOGO	Necessary	68.10 FL	*68.10 FL
7	1		*TAILGATE VALVE MATIC EMBLEM	Necessary	60.00 FL	*60.00 FL
8	1		*TAILGATE ELEGANCE EMBLEM	Necessary	75.00 FL	*75.00 FL
9	1		*TAILGATE INNER LOCK	Damaged	416.80 FL	*416.80 FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	366.20 FL	*366.20 FL
11	1		*TAILGATE INNER TRIM BOARD	Twisted	467.30 FL	*467.30 FL
12	1		*REAR BUMPER	Distorted	745.10 FL	*745.10 FL
13	2		*REAR BUMPER DAMPERS	Bent / Twisted	170.00 FL	*170.00 FL
14	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 FL	*- FL
15	2		*REAR BUMPER REFLECTORS	Cracked	120.00 FL	*120.00 FL
16	1		*REAR END PANEL OUTER	Badly Dented	542.00 FL	*542.00 FL
17	1		*REAR END PANEL LOWER	Repair	389.20 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Twisted	381.80 FL	*381.80 FL
19	2		*TAILLAMPS	Not Necessary	790.00 FL	*- FL
20	2		*REAR FENDER INNER TRIM BOARDS	Deformed / Twisted	1,310.60 FL	*1,310.60 FL
21	1		*REAR FLOOR PANEL	Repair	1,410.80 FL	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	455.20 FL	*- FL
23	1		*FRONT BUMPER	Deformed / Torn	788.20 FL	*788.20 FL
24	1		*FRONT BUMPER SPONGE	Torn	182.00 FL	*182.00 FL
25	1		*FRONT BUMPER REINFORCEMENT	Repair	398.20 FL	*- FL
26	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
27	1		*FRONT GRILLE	Cracked	355.20 FL	*355.20 FL
28	1		*HEADLAMP O/S	Cracked	2,120.60 FL	*2,120.60 FL
29	1		*FRONT SUPPORT PANEL	Repair	755.30 FL	*- FL
30	1		*REAR LICENCE PLATE	Serviceable	50.00 FS	*- FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*20.00 FS
33	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*SET REAR BUMPER REVERSE SENSOR	Malfunction	280.00 FS	*250.00 FS
36	1		*SET REAR REVERSE CAMERA	Serviceable	450.00 FS	*- FS
37	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*FRONT BUMPER LICENCE PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,567.30	10,915.70
- List Item Discount on L Items 25.00/25.00% (\$)	4,121.83	2,626.43
Total Parts (\$)	13,445.47	8,289.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	80.00	30.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REFIX TAILGATE MECHANISM	New	100.00	60.00
5	TO REMOVE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO REMOVE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO REMOVE & REFIX FUEL TANK	New	100.00	0.00
8	TO REMOVE & REFIX REAR REVERSE CAMERA	New	100.00	0.00
9	TO SPRAY ANTI-RUST PROOFING	New	120.00	60.00
10	TO DIAGNSIS & REPROGRAMME SYSTEM	New	180.00	0.00
11	LABOUR FOR PANEL BEATING	New	1,800.00	1,000.00
12	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,600.00
Gross Labour Cost (\$\$)			4,700.00	2,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >