

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24100267/KVP3M4**Date:** 06/11/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001928841		
Claimant Vehicle No :	SLA8339Z	Insured Vehicle No :	SLM3020L		
Date of Loss:	12/10/2024	Nature of Claim:	TP	Claim No:	376762

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA8339Z	Engine No:	8ARZ074017
Make & Model:	TOYOTA LEXUS, 2.0 IS200T EXECUTIVE (A)	Chassis No:	JTHBA1D2205050021
Reg. Date:	08/05/2017 (Man. Year: 2017)	Odometer:	89650 km
Colour:	Metallic Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,576.90	10,606.64	4,970.26	31.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,460.00	860.00	37.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,896.90	12,066.64	5,830.26	32.58
Approved Total (Overridden) (S\$)		8,900.00		
Nett Amount (S\$)	17,896.90	8,900.00	8,996.90	50.27

INSPECTION

Date of Assignment:	16/10/2024		
Date Inspected:	15/10/2024	Inspected At:	GUAN MOTOR WORKS (HQ) 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2024)
Parts:	143	TOYOTA LEXUS 2.0 IS200T EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA8339Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cracked	1,640.40 FL	*1,520.80 FL
2	2		*REAR BUMPER SIDE REFLECTOR	Serviceable	466.40 FL	*- FL
3	2		*REAR BUMPER REVERSE SENSOR	Cut	1,260.80 FL	*1,002.80 FL
4	1		*REAR BUMPER LOWER BLACK SPOILER	Dented	806.60 FL	*806.60 FL
5	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FL	*80.00 FL
6	2		*REAR BUMPER SIDE RETAINER	Serviceable	438.20 FL	*- FL
7	1		*REAR BUMPER INNER FOAM	Cracked	155.70 FL	*155.70 FL
8	1		*REAR BUMPER INNER REINFORCEMENT	Bent	733.30 FL	*733.30 FL
9	1		*TAILLAMP	N/S MtgCracked/O/S Serviceable	3,913.20 FL	*1,793.80 FL
10	1		*REAR BOOT LID	Buckled	1,838.80 FL	*1,838.80 FL
11	1		*REAR BOOT SIDE LAMP	N/S MtgCracked/O/S Serviceable	2,190.40 FL	*950.60 FL
12	1		*REAR BOOT TOP CENTRE LEXUS LOGO	Necessary	99.40 FL	*99.40 FL
13	1		*REAR BOOT LH LEXUS EMBLEM	Necessary	94.70 FL	*94.70 FL
14	1		*REAR BOOT RH IS200T EMBLEM	Necessary	110.00 FL	*110.00 FL
15	2		*REAR BOOT HINGE	Repair	621.20 FL	*- FL
16	1		*SET REAR BOOT INNER TRIM CLIPS	Not Necessary	80.00 FL	*- FL
17	1		*REAR BOOT TOP LOCK	Dented	691.90 FL	*691.90 FL
18	1		*REAR END PANEL	Bent	1,249.60 FL	*1,249.60 FL
19	1		*REAR END PANEL TOP GARNISH	Dented	440.60 FL	*440.60 FL
20	1		*REAR BOOT WEATHERSTRIP (50%) (SN)	Dented/Cut	329.80 FN	*164.90 F
21	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.
					Sub Total (\$\$)	17,301.00 11,763.50
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,691.12 1,156.86
					- Nett Item Discount on N Items 10.00/0.00% (\$\$)	32.98 0.00
					Total Parts (\$\$)	15,576.90 10,606.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE/REFIT, PANEL BEATING, CUTTING WELDING AND REPLACEMENT OF DAMAGES	New	1,000.00	600.00
2	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	1,000.00	660.00
3	TO REMOVE, REFIX AND RESET REVERSE SENSORS	New	100.00	60.00
4	TO CHECK WIRINGS & LIGHTINGS	New	40.00	20.00
5	TO REMOVE, REFIX REAR UPHOLSTERY & ATTACHMENTS	New	100.00	60.00
6	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	60.00
Gross Labour Cost (\$\$)			2,320.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >