

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100270/UMA3Q2
Date: 20/11/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230068903		
Claimant Vehicle No :	PC7133Z	Insured Vehicle No :	SNL3444D		
Date of Loss:	08/10/2024	Nature of Claim:	TP	Claim No:	6862314216SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC7133Z		
Make & Model:	MERCEDES-BENZ V220D, 2.1 D EXTRA-LONG (A)	Engine No:	65195034230330
Reg. Date:	01/06/2018 (Man. Year: 2017)	Chassis No:	WDF44781523342875
Colour:	Black	Odometer:	330531 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,774.50	1,548.00	3,226.50	67.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	470.00	610.00	56.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,854.50	2,018.00	3,836.50	65.53
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	5,854.50	1,600.00	4,254.50	72.67
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	16/10/2024	
Date Inspected:	16/10/2024 Inspected At:	Quan De Motor Trading BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883 Singapore 417883
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,455.00 FL	*1,455.00 FL
2	1		*FRONT BUMPER BEAM	Repair	905.00 FL	*- FL
3	1		*HEADLAMP LH	Serviceable	2,680.00 FL	*- FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
5	1		*FRONT BUMPER PDC SENSOR	Malfunction	215.00 FL	*215.00 FL
					Sub Total (S\$)	5,305.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	172.00
					Total Parts (S\$)	1,548.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACE FRONT PDC SENSOR	New	50.00	30.00
3	TO DIAGNOSTIC & REPROGRAMME SYSTEM	New	100.00	0.00
4	LABOUR FOR PANEL BEATING WELDING AND RENEW PARTS	New	380.00	200.00
5	SPRAY PAINTING	New	500.00	220.00
Gross Labour Cost (\$\$)			1,080.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >