



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBG 2519Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SLIDING DOOR LH	TO REPAIR SEE LABOUR	\$2,955.30	\$0.00
1	REAR FENDER LH	DISTORTED	\$2,877.20	\$1,875.00
1	REAR RAILWAY PANEL	BENT	\$890.00	\$890.00
1	REAR RAILWAY PANEL END	CRACKED	\$160.00	\$160.00
1	TAILLAMP LH	CRACKED	\$350.00	\$350.00
	LESS 25.00% DISCOUNT		(\$1,808.13)	(\$818.75)
			\$5,424.37	\$2,456.25

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF SLIDING DOOR LH		\$1,200.00	\$500.00
	TO SPRAY PAINT AFFECTED AREA		\$1,200.00	\$400.00
	TUFF COAT		\$200.00	\$30.00
	WIRING CHECK		\$80.00	\$30.00
	REMOVE AND REFIX FRONT DOOR MECHANISM	NOT NECESSARY	\$120.00	\$0.00
			\$2,800.00	\$960.00

GRAND TOTAL			\$8,224.37	\$3,416.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,700.00

Report Ref No: CS/SMO24100274/Avp3e2

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.