

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100276/KQP3M4**Date:** 23/10/2024**REFERENCE**

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SHD5146P **Insured Vehicle No :** SLH5963D
 Date of Loss: 15/10/2024 Nature of Claim: TP Claim No: DMPC2401387H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD5146P**
 Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2B70642
 Reg. Date: 01/11/2018 (Man. Year: 2018) Chassis No: JTDKB3FU503076410
 Colour: Metallic Pearl White/Red Odometer: 623711 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: LAUFENN 9 mm Rear Left Side: LAUFENN 9 mm
 Front Right Side: LAUFENN 9 mm Rear Right Side: LAUFENN 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,409.56	4,155.55	3,254.01	43.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	810.00	2,780.00	77.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,999.56	4,965.55	6,034.01	54.86
Approved Total (Overridden) (S\$)		3,950.00		
(S\$)	10,999.56	3,950.00	7,049.56	64.09
+ GST 9.00/9.00% (S\$)	989.96	355.50	634.46	64.09
Nett Amount (S\$)	11,989.52	4,305.50	7,684.02	64.09

INSPECTION

Date of Assignment: 15/10/2024
 Date Inspected: 15/10/2024 Inspected At: TRANS-CAB AUTO SERVICES PTE LTD (HQ)
 2 ANG MO KIO STREET 63
 SINGAPORE 569111
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2024)
Parts: 144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD5146P)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, FRONT BUMPER	Bent	653.31 FL	*653.31 FL
2	1		*ABSORBER, FRONT BUMPER ENERGY	Cracked	100.17 FL	*100.17 FL
3	1		*REINFORCEMENT SUB-ASSY, FRONT BUMPER	Repair	902.16 FL	*- FL
4	1		*STAY SUB-ASSY, FRONT BUMPER, LH	Serviceable	59.85 FL	*- FL
5	1		*BRACKET, FRONT BUMPER SIDE, LH	Distorted	74.97 FL	*74.97 FL
6	1		*COVER, FRONT BUMPER HOLE, LH	Missing	37.07 FL	*37.07 FL
7	1		*COVER SUB-ASSY, FRONT PILLAR, UPR LH	Serviceable	126.74 FL	*- FL
8	1		*SUPPORT, RADIATOR, UPPER LH	Serviceable	99.33 FL	*- FL
9	1		*HOOD SUB-ASSY	Repair	1,243.20 FL	*- FL
10	1		*HINGE ASSY, HOOD, LH	Repair	74.34 FL	*- FL
11	1		*HINGE ASSY, HOOD, RH	Repair	74.34 FL	*- FL
12	1		*LAMP ASSY, FOG, LH	Mtg Cracked	1,200.78 FL	*1,200.78 FL
13	1		*UNIT ASSY, HEADLAMP, LH	Mtg Cracked	3,325.56 FL	*3,325.56 FL
14	1		*FENDER SUB-ASSY, FRONT LH	Repair	1,236.69 FL	*- FL
15	1		*EMBLEM, SIDE PANEL LH	Necessary	68.88 FL	*68.88 FL
16	1		*LINER, FRONT FENDER, LH	Serviceable	255.36 FL	*- FL
17	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
18	1		*FENDER LINER CLIP	Not Necessary	130.00 FS	*- FS
19	1		*FRT LH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,792.75	5,520.74
- List Item Discount on L Items 25.00/25.00% (S\$)	2,383.19	1,365.19
Total Parts (S\$)	7,409.56	4,155.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,400.00	350.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	440.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
			Gross Labour Cost (\$\$)	3,590.00
				810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >