

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24060217/APA3Q2**Date:** 18/12/2024REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7240084255
Claimant Vehicle No : SMQ7536G **Insured Vehicle No :** SNL6622L
 Date of Loss: 24/06/2024 Nature of Claim: TP Claim No: 8756899505SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ7536G**
 Make & Model: AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZC32621
 Reg. Date: 29/11/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V0KA117900
 Colour: Blue Odometer: 44631 km
 Engine Capacity: 999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,804.00	8,282.64	4,521.36	35.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,902.00	2,642.00	2,260.00	46.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,706.00	10,924.64	6,781.36	38.30
+ GST 9.00/9.00% (S\$)	1,593.54	983.22	610.32	38.30
Nett Amount (S\$)	19,299.54	11,907.86	7,391.68	38.30
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		12,150.04		

INSPECTION

Date of Assignment: 28/06/2024
 Date Inspected: 28/06/2024 Inspected At: Premium Automobiles Pte Ltd (HQ)
 55 UBI ROAD 1
 Singapore 408699
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,411.00 FS	*1,928.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	209.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION -RH	Damaged	49.00 FS	*38.56 FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	373.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -RH	Not Necessary	357.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	236.00 FS	*- FS
7	1		*FRONT FENDER RH	Dented	1,016.00 FS	*812.80 FS
8	1		*FRONT FENDER ATTACHMENT PARTS RH	Not Necessary	85.00 FS	*- FS
9	1		*FRONT FENDER BRACKET -RH REAR	Not Necessary	45.00 FS	*- FS
10	1		*FRONT FENDER BRACKET -RH FRONT	Not Necessary	74.00 FS	*- FS
11	8		*FRONT FENDER RIVET-RH	Not Necessary	34.00 FS	*- FS
12	1		*FRONT FENDER SEAL -RH	Not Necessary	43.00 FS	*- FS
13	1		*FRONT FENDER BRACE -RH	Bent	122.00 FS	*97.20 FS
14	1		*FRONT FENDER CLOSING ELEMENT-RH	Damaged	76.00 FS	*60.80 FS
15	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	204.00 FS	*- FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS-RH	Not Necessary	67.00 FS	*- FS
17	1		*LED HEADLIGHT -RH	Cut	6,647.00 FS	*5,317.60 FS
18	1		*LIFT CYLINDER -RH	Not Necessary	170.00 FS	*- FS
19	1		*LIFT CYLINDER HOSE-RH	Not Necessary	86.00 FS	*- FS
20	1		*SUNDRIES	Necessary	500.00 FS	*26.88 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **12,804.00** **8,282.64**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,800.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			4,902.00	2,642.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >