

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: _____

at Work / s _____

of _____

Insured: _____

Policy No _____

Claim No _____

Sum Insured _____ Excess: _____

(Client Record)

Make of Vehicle _____

(Policy Condition)

N/S	O/S

Remark: Tereh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBD9119M Yr Regn: 2016 / May

Type: M.Car / M.Cycle / Bus (Van) / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace cc 2982

Colour White A/C: Insured / Std / NI / NA

Sp. Reading 201444 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02P700190214

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 RISC

R: 195 RISC

BS / DUN / EXNOVA / GY / FS / IZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Cordos

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.A.

15/10/24

Survey held at

JL Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/4/24

COE Expiry

Estimate given during : Yes (✓)

1st Survey : No (✓)

MV: 24K

PV: 4.6K

Nett: 19.4K

147D

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + R8. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Report Form:


Report Form:

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 14.10.2024

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : GBD9119M
MODEL : TOYOTA HIACE
DATE OF ACCIDENT : 14.10.2024
TIME OF ACCIDENT : 13:15 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,210.70	\$ 2,210.70
2	TAILGATE OUTER MOULDING <i>not mounted</i>	1	\$ 364.90	\$ 364.90
3	TAILGATE OUTER HANDLE <i>new</i>	1	\$ 97.80	\$ 97.80
4	TAIGATE NUMBER PLATE LAMP <i>new</i>	2	\$ 65.50	\$ 131.00
5	TAILGATE LOGO <i>new</i>	1	\$ 70.50	\$ 70.50
6	TAILGATE REVERSE CAMERA <i>new</i>	1	\$ 894.20	\$ 894.20
7	TAILGATE CORNER GARNISH <i>LH cracked</i>	2	\$ 185.90	\$ 371.80
8	TAILGATE STOPPER (UPPER SIDE) <i>3pc</i>	2	\$ 24.10	\$ 48.20
9	TAILGATE SIDE STOPPER (LOWER) <i>2pc</i>	2	\$ 28.60	\$ 57.20
10	TAILGATE INNER BOARD <i>torn</i>	1	\$ 388.70	\$ 388.70
11	TAILGATE WEATHERSTRIP <i>torn</i>	1	\$ 397.80	\$ 397.80
12	TAILGATE WEATHERSTRIP PROTECTOR <i>new</i>	1	\$ 271.60	\$ 271.60
13	TAILGATE INNER LOCK <i>new</i>	1	\$ 354.60	\$ 354.60
14	TAILGATE LOCK MOTOR <i>new</i>	1	\$ 545.00	\$ 545.00
15	TAILGATE LOWER LOCK <i>new</i>	1	\$ 254.10	\$ 254.10
16	TAIL LAMP <i>LH cracked</i>	2	\$ 355.20	\$ 710.40
17	TAIL LAMP PANEL LH <i>new</i>	1	\$ 419.80	\$ 419.80
18	TAILLAMP LOWER GARNISH <i>LH cracked</i>	2	\$ 257.40	\$ 514.80
19	TAILLAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 53.70	\$ 107.40
20	REAR SIDE PANEL LH <i>new</i>	1	\$ 1,828.90	\$ 1,828.90
21	REAR SIDE PANEL AIR VENT LH <i>new</i>	1	\$ 185.70	\$ 185.70

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : GBD9119M
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 14.10.2024
 TIME OF ACCIDENT : 13:15 HOURS

22	REAR BUMPER <i>Dented</i>	1	\$ 497.00	\$ 497.00	-
23	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 47.50	\$ 95.00	+
24	REAR END PANEL (EXTEND) <i>LH Dented</i>	1	\$ 428.10	\$ 428.10	✓
25	REAR END PANEL (INNER) <i>Repr</i>	1	\$ 1,124.80	\$ 1,124.80	+
26	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 498.60	\$ 498.60	✓
27	REAR FLOOR PANEL <i>Repr</i>	1	\$ 1,966.20	\$ 1,966.20	+
28	REAR FLOOR PANEL MAT <i>new</i>	1	\$ 1,215.10	\$ 1,215.10	-

TOTAL PRICE \$ 16,049.90
 LESS 25% \$ 4,012.48
SUB TOTAL PRICE \$ 12,037.43

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	30
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
3	REAR SIDE PANEL SEALANT (OUTER) <i>new</i>	2	\$ 150.00	\$ 300.00	+
4	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
5	TAILLAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	20
6	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
7	TAILGATE OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
8	TAILGATE TOP TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
9	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
10	TAILGATE STICKER '70KM/H' <i>new</i>	1	\$ 30.00	\$ 30.00	15
11	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
12	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	30
13	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	60
14	REAR END PANEL (EXTEND) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
15	REAR FLOOR PANEL TOP COVER (BOARD) SPECAIL TYPE <i>new</i>	1	\$ 800.00	\$ 800.00	+
16	REAR STICKER (SPECAIL TYPE) <i>new</i>	1	\$ 400.00	\$ 400.00	120

TOTAL \$ 2,430.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,400.00	<i>800</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : GBD9119M
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 14.10.2024
 TIME OF ACCIDENT : 13:15 HOURS

2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	700
3	WIRNING, BULB CHECKING	\$ 80.00	30
4	TRANSFER TAILGATE MECHAISM	\$ 80.00	60
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	+
6	REMOVE AND REFIX ROOF LINING	\$ 100.00	+
7	REMOVE AND REFIX FUEL TANK	\$ 100.00	+
8	REMOVE AND REFIX REAR FLOOR BAORD	\$ 350.00	+
9	REMOVE AND REFIX REVERSE CAMERA	\$ 120.00	50
10	REAR CHASSIS ALIGHMENT	\$ 250.00	+
11	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 5,900.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,467.43
 TOTAL LABOUR COST : \$ 5,900.00
 TOTAL REPAIR COST : \$ 20,367.43

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Cj
 1/5 15/10/24
 06 Days.