



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100283/Uqh3e2
75 BRAS BASAH ROAD	Date:	30/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBM 6777K	Veh. Inspected	GBJ 3415R
Policy No.	-	Coverage	0
Claim No.	MT/1292562-001	Excess	\$0.00
Assign From	JEFF LIN	Assign Date	16/10/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE (M)	C.C	2982
Engine No.	1KD2848861	Year of Reg.	28/03/2019
Chassis No.	JTFHT02P300248643	Colour	WHITE
Odometer	134479 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	BLACKHAWK	6
L/H Front Tyre	195R15	BLACKHAWK	6
R/H Rear Tyre	195R15	OHTSU	6
L/H Rear Tyre	195R15	OHTSU	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/08/2024	Inspection Date	16/10/2024 (09:57)
Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days