



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100285/Uvh3e2
75 BRAS BASAH ROAD	Date:	24/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBL 9846E	Veh. Inspected	SKZ 8638R
Policy No.	-	Coverage	0
Claim No.	MT/1299894-002	Excess	\$0.00
Assign From	AMANDA CHOOI	Assign Date	16/10/2024

### 2. Vehicle Details

Make & Model	TOYOTA COROLLA AXIO (A)	C.C	1496
Engine No.	2NR8507355	Year of Reg.	05/02/2016
Chassis No.	NRE1610010137	Colour	BLACK
Odometer	584939 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	GITI	6
L/H Front Tyre	185/60R15	GITI	6
R/H Rear Tyre	185/60R15	GITI	6
L/H Rear Tyre	185/60R15	GITI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	14/10/2024	Inspection Date	16/10/2024 (10:01)
Survey held at	V.Z AUTOMOTIVE PTE LTD - PREMIER@8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days