



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKL 5855Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	BUCKLED	\$1,100.00	\$1,100.00
1	FRONT HEADLAMP	MTG CRACKED	\$2,000.00	\$2,000.00
1	FRONT HEADLAMP BRACKET	SERVICEABLE	\$35.00	\$0.00
1	FRONT BUMPER EMBLEM (LOGO)	NECESSARY	\$170.00	\$170.00
1	FRONT RADIATOR RUBBER GANISH	NECESSARY	\$190.00	\$190.00
1	FRONT BUMPER BEAM	BENT	\$320.00	\$320.00
2	FRONT GRILLE @\$190.00	DENTED/CUT	\$380.00	\$380.00
	LESS 10.00% DISCOUNT		(\$419.50)	(\$416.00)
			\$3,775.50	\$3,744.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	NUMBER PLATE (SN)	DENTED	\$30.00	\$30.00
			\$30.00	\$30.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RENEW ABOVE PARTS		\$500.00	\$250.00
	TO RESPRAY ABOVE PARTS		\$300.00	\$250.00
			\$800.00	\$500.00
GRAND TOTAL			\$4,605.50	\$4,274.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,400.00
Report Ref No: CS/SMO24100287/Kqp3e2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.