



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNN 6521J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR LH	DENTED	4,138.20	3,762.00
1	REAR DOOR WEATHERSTRIP LH	NOT NECESSARY	220.00	-
1	REAR DOOR RUBBER STOPPER LH	NOT NECESSARY	12.00	-
1	REAR DOOR INNER PLASTIC SEAL COVER LH	NOT NECESSARY	30.00	-
1	SIDE SKIRT GARNISH LH	TO REPAIR SEE LABOUR	310.20	-
	LESS 10% DISCOUNT		-471.04	-376.20
			4,239.36	3,385.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR DOOR INNER TRIM BOARD CLIP LH (SN)	NOT NECESSARY	50.00	-
1	SET SIDE SKIRT GARNISH CLIP LH (SN)	NOT NECESSARY	50.00	-
			100.00	-
	<u>LABOUR</u>			
	TO REMOVE & REFIX ACCIDENT DAMAGED PARTS & REALIGN AFFECTED AREA. INCLUSIVE OF THE REPAIR OF SIDE SKIRT GARNISH LH.		400.00	300.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA.		600.00	400.00
	TO REMOVE & REFIX DOOR MECHANISM.		80.00	60.00
	TO RUST PROOF AFFECTED AREA.	NOT NECESSARY	50.00	-
			1,130.00	760.00
	GRAND TOTAL		5,469.36	4,145.80
RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,145.80

Report Ref No. CS/INC24100289/Anh3m4(N)

TOTAL FOR SPARE PARTS: \$ 4,339.36 \$ 3,385.80

TOTAL FOR LABOUR : \$ 1,130.00 \$ 760.00

TOTAL REPAIR COST: \$ 5,469.36 \$ 4,145.80

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.