



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMP 6643S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DEFORMED	\$2,261.93	\$791.00
2	FRONT BUMPER SIDE HOLDER @\$132.36	DAMAGED	\$264.72	\$65.00
1	FRONT BUMPER LOWER LIP	CUT	\$580.75	\$469.00
1	FRONT LH HEADLAMP	CUT	\$5,056.32	\$3,378.00
1	FRONT LH FENDER	DENTED	\$949.90	\$799.00
1	FRONT LH FENDER INNER SHIELD	DEFORMED	\$272.20	\$272.20
1	FRONT LH FENDER INNER SHIELD CLIPS	NECESSARY	\$5.75	\$5.75
1	FRONT LH FENDER HYBRID EMBLEM	NECESSARY	\$50.71	\$50.71
1	FRONT LH FENDER SIDE GARNISH	CUT	\$165.02	\$165.02
1	FRONT LH TYRE	NOT NECESSARY	\$552.00	\$0.00
1	FRONT LH SHOCK ABSORBER	NOT NECESSARY	\$567.64	\$0.00
1	FRONT LH LOWER ARM	BENT	\$874.11	\$665.00
1	FRONT LH KNUCKLE ARM	DAMAGED	\$803.27	\$649.00
1	FRONT LH KNUCKLE ARM BEARING	DAMAGED	\$801.66	\$442.00
1	FRONT BONNET	TO REPAIR SEE LABOUR	\$1,395.06	\$0.00
1	FRONT BONNET SIDE MOULDING	NECESSARY	\$107.18	\$107.18
1	FRONT LH FENDER TOP GARNISH	DEFORMED	\$67.73	\$67.73
	<b>LESS 25.00% DISCOUNT</b>		(\$3,693.99)	(\$1,981.65)
			<b>\$11,081.96</b>	<b>\$5,944.94</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LH SPORT RIM (SN)	CUT	\$1,835.58	\$880.00
			<b>\$1,835.58</b>	<b>\$880.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE + REINSTALL FRONT LH SUSPENSION		\$400.00	\$200.00
	REMOVE, REPLACE + REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET		\$1,500.00	\$600.00
	RESPRAY PAINTING		\$1,400.00	\$800.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WHEEL ALIGNMENT		\$100.00	\$80.00
			\$3,400.00	\$1,680.00
GRAND TOTAL			\$16,317.54	\$8,504.94
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$6,800.00
Report Ref No: CS/INC24100290/Anh3e2				

TOTAL FOR SPARE PARTS: \$ 12,917.54 \$ 6,824.94  
TOTAL FOR LABOUR : \$ 3,400.00 \$ 1,680.00  
TOTAL REPAIR COST: \$ 16,317.54 \$ 8,504.94

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.