

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURANCE	CE LTD	Ref:	CS/INC24100290/Anh3e2	
	75 BRAS BASAH RO		Date:	27/12/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJT 4833M	Veh. Inspected	SMP 6643S	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1299828-002	Excess	\$0.00	
	Assign From	RAJESWARY	Assign Date	15/10/2024	
2. Vehicle Details					
	Make & Model	TOYOTA C-HR	C.C	1797	
	Engine No.	2ZR2C69751	Year of Reg.	08/10/2019	
	Chassis No.	ZYX102164212	Colour	YELLOW	
	Odometer	374116 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
			00000/540	6	
	R/H Front Tyre	225/50 R18	GOODYEAR	Ü	
	R/H Front Tyre L/H Front Tyre	225/50 R18 225/50 R18	GOODYEAR	6	
	L/H Front Tyre	225/50 R18	GOODYEAR	6	
4.	L/H Front Tyre R/H Rear Tyre	225/50 R18 225/50 R18	GOODYEAR GOODYEAR GOODYEAR	6 6	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/50 R18 225/50 R18 225/50 R18	GOODYEAR GOODYEAR GOODYEAR of Damages	6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/50 R18 225/50 R18 225/50 R18  Description of ED DAMAGES AT THE FRONT N/S PO	GOODYEAR GOODYEAR GOODYEAR of Damages	6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	225/50 R18 225/50 R18 225/50 R18  Description of ED DAMAGES AT THE FRONT N/S PO	GOODYEAR GOODYEAR GOODYEAR of Damages RTION.	6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	225/50 R18 225/50 R18 225/50 R18  Description of ED DAMAGES AT THE FRONT N/S PO	GOODYEAR GOODYEAR GOODYEAR of Damages RTION.	6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAINI MAGES SEE DETAILS	225/50 R18 225/50 R18 225/50 R18  Description of the properties of	GOODYEAR GOODYEAR GOODYEAR of Damages RTION. formation Inspection Date	6 6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAINI AGES SEE DETAILS  Accident Date	225/50 R18 225/50 R18 225/50 R18  Description of the properties of	GOODYEAR GOODYEAR GOODYEAR of Damages RTION. formation Inspection Date SHOP	6 6 6	
THE DAM  5.  5a. A) T	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  E-VEHICLE SUSTAINING AGES SEE DETAILS  Accident Date Survey held at	225/50 R18 225/50 R18 225/50 R18  Description of the second of the secon	GOODYEAR GOODYEAR GOODYEAR FOR DAMAGES RTION. Formation Inspection Date SHOP  DAMAGES SHOP  DAMAGES SHOP  DAMAGES DAMA	6 6 6 17/10/2024 (17:29)	

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days