



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBF 2486M

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FORK INNER TUBES	BENT	\$440.00	\$250.00
2	FORK OUTER TUBES	O/S BENT	\$460.00	\$230.00
1	FORK UNDER BRACKET	BENT	\$245.00	\$205.00
1	FRONT FENDER	CRACKED	\$165.00	\$115.00
1	FRONT RIM	TO REPAIR SEE LABOUR	\$580.00	\$0.00
1	FRONT RIM SHAFT	NOT NECESSARY	\$125.00	\$0.00
1	FRONT RIM BEARING	NOT NECESSARY	\$110.00	\$0.00
1	METER ASSY	CUT	\$480.00	\$480.00
1	HEADLAMP ASSY	NOT NECESSARY	\$580.00	\$0.00
1	LAMPSTAY	NOT NECESSARY	\$485.00	\$0.00
1	FRONT SIGNALS	NOT NECESSARY	\$160.00	\$0.00
1	HANDLE-BAR	BENT	\$285.00	\$220.00
1	HANDLE-BAR END	MISSING	\$220.00	\$50.00
1	SET HAND GRIP	CUT	\$105.00	\$80.00
1	CLUTCH LEVER	CUT	\$465.00	\$115.00
2	SIDE MIRROR	BROKEN	\$225.00	\$150.00
1	FRONT LOWER COVER	CUT	\$285.00	\$285.00
2	FUEL TANK SIDE COVER	CRACKED	\$520.00	\$520.00
1	ENGINE COVER	TO REPAIR SEE LABOUR	\$580.00	\$0.00
2	FRONT FOOTRESTS	CUT	\$280.00	\$150.00
2	FRONT FOOTREST BRACKETS	SERVICEABLE	\$480.00	\$0.00
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	\$165.00	\$0.00
1	GEAR PEDAL	NOT NECESSARY	\$105.00	\$0.00
1	REAR COVER	CUT	\$285.00	\$285.00
1	EXHAUST ASSY (YOSHIMURA)	DENTED	\$2,800.00	\$1,600.00
	<b>LESS 10.00% DISCOUNT</b>		(\$1,063.00)	(\$473.50)
			<b>\$9,567.00</b>	<b>\$4,261.50</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	NOT NECESSARY	\$38.00	\$0.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FORK OILS (SN)	NOT NECESSARY	\$30.00	\$0.00
2	FORK OIL SEALS (SN)	NOT NECESSARY	\$56.00	\$0.00
1	SET STEERING CONE (SN)	NECESSARY	\$140.00	\$60.00
1	E.R.P. IU (SN) (KIV)	BROKEN	\$230.00	\$0.00
1	REAR BOX (SN)	CUT	\$580.00	\$300.00
1	REAR BOX BRACKET (SN)	BENT	\$180.00	\$100.00
			\$1,254.00	\$460.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO RESPRAY PAINTING		\$680.00	\$200.00
	TO REPAIR BODY FRAME	NOT NECESSARY	\$420.00	\$0.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT RIM, ENGINE COVER AND BRAKE PEDAL		\$480.00	\$300.00
			\$1,660.00	\$500.00
<b>GRAND TOTAL</b>			<b>\$12,481.00</b>	<b>\$5,221.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>\$1,800.00</b>
Report Ref No: CS/INC24100292/Uqh3e2				

TOTAL FOR SPARE PARTS: \$ 10,821.00 \$ 4,721.50  
TOTAL FOR LABOUR : \$ 1,660.00 \$ 500.00  
TOTAL REPAIR COST: \$ 12,481.00 \$ 5,221.50

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repossibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.