

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100293/DVP3E2
Date: 08/01/2025REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SH7378Y	Insured Vehicle No :	SLC3277R
Date of Loss:	12/10/2024	Nature of Claim:	TP
		Claim No:	DMPC2401380H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7378Y	Engine No:	G4LEKU417043
Make & Model:	HYUNDAI IONIQ, 1.6 (A)	Chassis No:	KMHC851CVLU192010
Reg. Date:	28/01/2021 (Man. Year: 2019)	Odometer:	383922 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,600.59	13,091.54	14,509.05	52.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,920.00	2,030.00	3,890.00	65.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	33,520.59	15,121.54	18,399.05	54.89
Approved Total (Overridden) (\$\$)		12,100.00		
(\$\$)	33,520.59	12,100.00	21,420.59	63.90
+ GST 9.00/9.00% (\$\$)	3,016.85	1,089.00	1,927.85	63.90
Nett Amount (\$\$)	36,537.44	13,189.00	23,348.44	63.90

INSPECTION

Date of Assignment:	16/10/2024		
Date Inspected:	17/10/2024	Inspected At:	BIFROST AUTO PTE LTD - LOYANG (HQ) 59 Loyang Drive Level 4 Room 7 Singapore 508969
Estimated Period of Repair:	9.0 days		

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2025)
Parts:	143	HYUNDAI IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH7378Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Bent / Mtg Broken	481.10 FL	*481.10 FL
2	1		*FRONT BUMPER TOP COVER	Not Necessary	476.30 FL	*- FL
3	1		*FRONT BUMPER MOULDING CENTRE UPPER	Mtg Broken	368.50 FL	*368.50 FL
4	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	35.00 FL	*- FL
5	1		*FRONT BUMPER BRACKET (LH)	Broken	28.00 FL	*28.00 FL
6	1		*FRONT BUMPER RETAINER MOUNTING (LH)	Not Necessary	65.30 FL	*- FL
7	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
8	1		*FRONT BUMPER GRILLE (LH)	Dislodged	186.90 FL	*186.90 FL
9	1		*FRONT BUMPER AIR DUCT (LH)	Not Necessary	153.80 FL	*- FL
10	1		*DAY LIGHT, LH	Mtg Broken	642.50 FL	*642.50 FL
11	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	1,139.30 FL	*1,139.30 FL
12	1		*HEADLAMP (LH)	Mtg Broken	3,987.30 FL	*3,987.30 FL
13	1		*FRT PILLAR UPPER COVER - OUTER (LH)	Dislodged	89.60 FL	*89.60 FL
14	1		*FRONT FENDER (LH)	Dented	490.70 FL	*490.70 FL
15	1		*FRONT FENDER APRON PANEL (LH)	Not Necessary	756.20 FL	*- FL
16	1		*FRONT FENDER APRON PANEL UPPER (LH)	Not Necessary	329.00 FL	*- FL
17	1		*FRONT FENDER SHIELD (LH)	Torn	164.70 FL	*164.70 FL
18	1		*FRT DOOR (LH)	Buckled	1,797.20 FL	*1,797.20 FL
19	1		*FRT DOOR RUBBER	Serviceable	250.00 FL	*- FL
20	1		*FRONT DOOR REGULATOR (LH)	Broken	750.40 FL	*750.40 FL
21	1		*FRONT DOOR POWER MOTOR, LH	Not Necessary	689.20 FL	*- FL
22	1		*FRONT DOOR HINGE UPPER (LH)	Not Necessary	165.76 FL	*- FL
23	1		*FRONT DOOR HINGE LOWER (LH)	Bent	153.70 FL	*153.70 FL
24	1		*FRONT DOOR CHECK (LH)	Bent	72.98 FL	*72.98 FL
25	1		*FRONT DOOR INNER LOCK (LH)	Damaged	385.60 FL	*385.60 FL
26	1		*FRONT DOOR OUTER HANDLE (LH)	Not Necessary	234.80 FL	*- FL
27	1		*FRONT DOOR MIRROR ASSY (LH)	Not Necessary	1,691.70 FL	*- FL
28	1		*FRONT DOOR TRIM BOARD (LH)	Mtg Broken	796.80 FL	*796.80 FL
29	1		*FRONT DOOR PROTECTOR (LH)	Bent / Cracked	186.20 FL	*186.20 FL
30	1		*FRONT DOOR OUTER MOULDING (LH)	Not Necessary	110.10 FL	*- FL
31	1		*ROCKER PANEL OUTER GARNISH	Punctured	715.60 FL	*715.60 FL
32	1		*ROCKER PANEL OUTER	Repair	1,799.60 FL	*- FL
33	1		*ROCKER PANEL INNER (LH)	Not Necessary	752.60 FL	*- FL
34	1		*ROCKER PANEL STEP GARNISH (FRONT) (LH)	Not Necessary	156.50 FL	*- FL
35	1		*FRONT WINDSCREEN MOULDING	Not Necessary	157.30 FL	*- FL
36	1		*FRONT WINDSCREEN PILLAR OUTER (LH)	Repair	3,764.90 FL	*- FL
37	1		*FRONT WHEEL RIM (LH)	Distorted	1,124.20 FL	*1,124.20 FL
38	1		*FRONT WHEEL HUB ASSY (LH)	Damaged	678.50 FL	*678.50 FL
39	1		*FRONT WHEEL HUB CAP	Dislodged	346.40 FL	*346.40 FL
40	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	372.50 FL	*372.50 FL
41	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	372.50 FL	*- FL
42	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,136.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*RACK & PINION ASSY	Not Necessary	2,387.40 FL	*- FL
44	1		*STG TIE END	Not Necessary	94.70 FL	*- FL
45	1		*STABILIZER BAR	Not Necessary	326.80 FL	*- FL
46	1		*STABILIZER BAR LINK	Not Necessary	92.10 FL	*- FL
47	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	596.80 FL	*596.80 FL
48	1		*KNUCKLE ARM (LH)	Distorted	663.60 FL	*663.60 FL
49	1		*ENGINE CROSSMEMBER	Not Necessary	1,803.90 FL	*- FL
50	1		*EMBLEM-BLUE DRIVE (LH)	Necessary	26.60 F	*26.60 FN
51	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
52	1		*FRONT WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS
53	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	34,409.84	16,345.68
- List Item Discount on L Items 20.00/20.00% (S\$)	6,809.25	3,248.82
- Nett Item Discount on N Items 0.00/20.00% (S\$)	0.00	5.32
Total Parts (S\$)	27,600.59	13,091.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	900.00
2	SPRAY PAINTING CHARGE	New	1,600.00	800.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	30.00
5	TOWING CHARGE	New	80.00	0.00
6	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
7	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE / REFIX UNDERCARRIAIGE (FRT)	New	400.00	150.00
10	REMOVE / REFIX RADIATOR	New	90.00	0.00
11	REMOVE / REFIX AIRCON & REFILL GAS	New	130.00	0.00
12	REMOVE / REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
13	REMOVE / REFIX DASHBOARD	New	350.00	0.00
14	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (S\$)			5,920.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >