



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO JQS 3391

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FRONT FORK TUBE ASSY	TO REPAIR SEE LABOUR	\$640.00	\$0.00
1	FORK UNDER BRACKET	SERVICEABLE	\$225.00	\$0.00
1	FRONT WHEEL RIM	TO REPAIR SEE LABOUR	\$495.00	\$0.00
1	FRONT RIM SHAFT	SERVICEABLE	\$105.00	\$0.00
1	FRONT RIM BEARING	NOT NECESSARY	\$88.00	\$0.00
1	FRONT BRAKE DISC	NOT NECESSARY	\$185.00	\$0.00
1	HANDLE BAR	BENT	\$145.00	\$145.00
1	SET HANDLE-BAR ENDS	CUT	\$125.00	\$38.00
1	SET HAND GRIP	NOT NECESSARY	\$90.00	\$0.00
1	HANDLE BAR INNER BRACKET	TO REPAIR SEE LABOUR	\$135.00	\$0.00
1	HEADLAMP ASSY	CRACKED	\$485.00	\$350.00
1	SET SIDE MIRRORS	CUT	\$110.00	\$68.00
1	SET FRONT SIGNALS	SERVICEABLE	\$140.00	\$0.00
1	FRONT SIGNAL LOWER GARNISH	CUT	\$105.00	\$105.00
1	FRONT SIDE LOWER COVER	CUT	\$125.00	\$125.00
1	BASKET	CUT	\$125.00	\$125.00
1	SET FAIRING ASSY	CRACKED	\$650.00	\$520.00
1	FRONT FOOTREST BRACKET	BENT	\$65.00	\$65.00
2	FRONT FOOTREST RUBBERS	TORN	\$70.00	\$70.00
1	GEAR PEDAL	SERVICEABLE	\$125.00	\$0.00
1	BRAKE PEDAL	BENT	\$165.00	\$140.00
1	REAR HANDLE	CUT	\$225.00	\$155.00
2	REAR FOOTREST	SERVICEABLE	\$80.00	\$0.00
2	REAR FOOTREST BRACKETS	SERVICEABLE	\$156.00	\$0.00
	LESS 10.00% DISCOUNT		(\$485.90)	(\$190.60)
			\$4,373.10	\$1,715.40

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	NECESSARY	\$38.00	\$20.00
2	FORK OILS (SN)	NOT NECESSARY	\$30.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FORK OIL SEALS (SN)	NOT NECESSARY	\$56.00	\$0.00
1	SET STEERING CONE (SN)	NOT NECESSARY	\$185.00	\$0.00
1	SET STICKER (SN)	NECESSARY	\$120.00	\$60.00
			\$429.00	\$80.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FORK TUBE ASSY, FRONT WHEEL RIM AND HANDLE BAR INNER BRACKET		\$480.00	\$300.00
	TO RE-ALIGN BODY FRAME	NOT NECESSARY	\$420.00	\$0.00
			\$980.00	\$300.00

GRAND TOTAL		\$5,782.10	\$2,095.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$900.00
Report Ref No: CS/INC24100295/Unh3e2			

TOTAL FOR SPARE PARTS: \$ 4,802.10 \$ 1,795.40
TOTAL FOR LABOUR : \$ 980.00 \$ 300.00
TOTAL REPAIR COST: \$ 5,782.10 \$ 2,095.40

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.