ASS. REC. BY:	S/LIP24100300/Kvh3
Kenneth	SIGNMENT
From: Date:	Veh No: GBJ FOOSAYRegn: OS, 19
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP WS TP RES TOD RES LEVA TINV I MV	Truck / Trailer or
To Inspect Vehicle No:	77)
at Workshop m/s 7/4/4	The state of the s
of 916m	105821 misured / Std / NI / NA
Insured: Yell	Sp.Reading T/Radio: Insured / Std / NI / NA Eng/No:
Policy No.	an and
Claims No. 1VS 2H 1968	Gen. Cond: Good/Fair/Poor/Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: Nill / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 205/55R16
Remark: The veh had commenced its N/S O/S	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA VMIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal. or Market Value: & 45/c	to regarded agent (A) accept. Any planted secures, August secures (August secure) 1 (Secured secure) 1 (Secured secure)
IDAC Accident Rport: Consistent? : Yes or No	Front Rear
GIA / PR Seen: Consistent?: Yes or No	mm NBa. 7 mm
Est. Repairs: 4-5days Res.: Yes or No	DOA // Visitati
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at D.O.I. 24/10/2024
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	Real TOIS THIS TUIC T Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	and the distriction of the distr
11/11 /1 / 1 B 63 and 1 f	
South Carry	
19/11/24 LS \$5500 confirmed with Jenny (red	7427, 57%)
R	
li.	to the second and the second s
	Section 1. The section of the sectio
	The second secon
Oate/Time, File Pass to? : Preli. Report Da	ays Of Repair:
; Final Report Re	CITAL ALL III
Outo/Time, File Return to?	Transportation
Add Fee:	: Site Insp (\$) _s+Rssi
Daniel Burner	: Interview (\$), Finds
Report Format :	Tech Invs (\$). Others
Lump Sum / I.B.I: (S	Weekend (\$
_	Note the contract of the contr

NOT Northasher 1/Ly & 6300/2 Purny After Pary 5day

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number: GBJ 7608A

S/N Parts Description 1 Rear tailgate RH 2 Rear tailgate LH 3 Rear tailgate logo 4 Rear tailgate Citroen emblem 5 Rear tailgate Berlingo emblem 6 Rear tailgate lock X2 7 Rear tailgate windscreen LH 8 Rear wiper arm 9 Rear wiper blade 10 Rear wiper arm cover 11 Rear tailgate rubber X2 12 Rear bumper 13 Rear bumper reinforcement 14 Rear bumper retainer X2 15 Rear bumper reverse sensor 16 Rear taillamp X2 17 Rear end panel 18 Rear No.plate lamp X2	Unit Price Amt \$1,620.00 \$1,620 \$1,550.00 \$1,550.00 \$1,550.00 \$1,550.00 \$1,98 \$98.00 \$1,99.00 \$109.00 \$1,28.00 \$128.00 \$1,28.00 \$128.00 \$1,20.00 \$720.00 \$1,08.00 \$10
Special Nett 1 Rear No.plate 2 Rear windscreen sealant X2	\$50.00 \$50.00 \$51 \$60.00 \$120.00 \$60sm \$110.00 \$170.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
 To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1

Labour

1 To remove and refit affected parts, cut and weld affected arears		\$900	3001
2 To spray paint on affected areas.			6001
3 To remove and refit rear windscreen		\$200	801
4 To transfer rear tailgate mechanism		\$200	1201
5 To remove and refit reverse sensor		\$100	501
6 Tuff coat		\$120	601
		\$2,420	
	12,927		Page 2