



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC24100301/Anh3e2(N)

Date: 21/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBS 6739P	Veh. Inspected	SNN 3651L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1299997-001	Excess (\$)	0.00
Assign From	RAJESWARY	Assign Date	16/10/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA	c.c	1490
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	MXPL101047933	Colour	GREY
Odometer	46919 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	TOYO	6 mm
L/H Front Tyre	185/65 R15	TOYO	6 mm
R/H Rear Tyre	185/65 R15	TOYO	6 mm
L/H Rear Tyre	185/65 R15	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/10/2024	Inspect Date / Time	17/10/2024 (01:27 PM)
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**