

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunost Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24100305/EQP3E2**Date:** 08/11/2024REFERENCE

Insured/Claimant:	HEE LI LING	Policy No:	MPC24A00127000		
Date of Loss:	12/10/2024	Nature of Claim:	OD	Claim No:	DMPC2401380H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC3277R				
Make & Model:	MERCEDES-BENZ E200 KOMPRESSOR, 1.8 (A)	Engine No:	27195631147145		
Reg. Date:	24/02/2009 (Man. Year: 2008)	Chassis No:	WDB2110412B399715		
Colour:	Black	Odometer:	212195 km		
Engine Capacity:	1796 cc				
Market Value/New Car Price:	S\$45,000.00				
Sum Insured (S\$):	Market Value/New Car Price				

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,750.50	11,777.50	6,973.00	37.19
Miscellaneous Items	100.00	80.00	20.00	20.00
Labour	3,800.00	1,100.00	2,700.00	71.05
Paintwork Labour	1,100.00	800.00	300.00	27.27
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,750.50	13,757.50	9,993.00	42.07
Approved Total (Overridden) (S\$)		11,000.00		
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	22,750.50	10,000.00	12,750.50	56.04
+ GST 9.00/9.00% (S\$)	2,047.55	900.00	1,147.55	56.05
Nett Amount (S\$)	24,798.05	10,900.00	13,898.05	56.04

INSPECTION

Date of Assignment:	16/10/2024	Present Location:	Convergence Automotive Pte Ltd (HQ)
Date Inspected:	17/10/2024	Inspected At:	Convergence Automotive Pte Ltd (HQ)
Estimated Period of Repair:	8.0 days		39 Woodlands Close, MEGA@Woodlands #01-24
			Singapore 737856

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2024)
Parts:	143	MERCEDES-BENZ E200 KOMPRESSOR 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC3277R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Repair	1,370.00 F	*- F
2	1		*FRT BUMPER (WCP)	Broken	1,500.00 F	*1,500.00 F
3	1		*SUPPORT PANEL LH (WCP)	Not Necessary	155.00 F	*- F
4	1		*SUPPORT PANEL RH (WCP)	Not Necessary	155.00 F	*- F
5	1		*SUPPORT PANEL CENTER (WCP)	Not Necessary	170.00 F	*- F
6	1		*REINFORCEMENT LH (WCP)	Not Necessary	145.00 F	*- F
7	1		*REINFORCEMENT RH (WCP)	Not Necessary	145.00 F	*- F
8	1		*REINFORCEMENT CENTER (WCP)	Not Necessary	200.00 F	*- F
9	1		*BUMPER SPRING (WCP)	Not Necessary	15.00 F	*- F
10	1		*BUMPER RETAINER RH (WCP)	Bent	35.00 F	*35.00 F
11	1		*BUMPER RETAINER LH (WCP)	Not Necessary	35.00 F	*- F
12	1		*BUMPER BRACKET MOUNTING RH (WCP)	Broken	120.00 F	*120.00 F
13	1		*BUMPER BRACKET MOUNTING LH (WCP)	Not Necessary	120.00 F	*- F
14	1		*TOWING COVER (WCP)	Missing	40.00 F	*40.00 F
15	1		*FOGLAMP COVER LH (WCP)	Not Necessary	55.00 F	*- F
16	1		*FOGLAMP COVER RH (WCP)	Missing	55.00 F	*55.00 F
17	1		*FOGLAMP CHROME TRIM GARNISH LH (WCP)	Not Necessary	160.00 F	*- F
18	1		*FOGLAMP CHROME TRIM GARNISH RH (WCP)	Missing	160.00 F	*160.00 F
19	1		*FOGLAMP COVER CHROME LH (WCP)	Not Necessary	155.00 F	*- F
20	1		*FOGLAMP COVER CHROME RH (WCP)	Missing	155.00 F	*155.00 F
21	1		*BUMPER LOWER GRILLE CENTER (WCP)	Not Necessary	105.00 F	*- F
22	1		*BUMPER LOWER GRILLE RH (WCP)	Not Necessary	95.00 F	*- F
23	1		*LICENSE PLATE HOLDER (WCP)	Not Necessary	275.00 F	*- F
24	1		*FENDER LH (WCP)	Not Necessary	1,000.00 F	*- F
25	1		*FENDER RH (WCP)	Broken	1,000.00 F	*1,000.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FENDER INNER SHIELD FRT RH (WCP)	Torn	110.00 F	*110.00 F
27	1		*FENDER INNER SHIELD REAR RH (WCP)	Not Necessary	110.00 F	*- F
28	1		*HEADLAMP RH (WCP)	Broken	1,900.00 F	*1,900.00 F
29	1		*HEADLAMP RH TRIM (WCP)	Not Necessary	95.00 F	*- F
30	1		*HEADLAMP WASHER NOZZLE LH (WCP)	Broken	200.00 F	*200.00 F
31	1		*HEADLAMP WASHER NOZZLE RH (WCP)	Broken	200.00 F	*200.00 F
32	1		*HEADLAMP WASHER NOZZLE CAP LH (WCP)	Missing	120.00 F	*120.00 F
33	1		*HEADLAMP WASHER NOZZLE CAP RH (WCP)	Missing	120.00 F	*120.00 F
34	1		*FRT RH ABSORBER (WCP)	Not Necessary	460.00 F	*- F
35	1		*FRT RH ABSORBER MOUNTING (WCP)	Not Necessary	230.00 F	*- F
36	1		*FRT RH KNUCKLE ARM (WCP)	Not Necessary	300.00 F	*- F
37	1		*FRT RH WHEEL BEARING (WCP)	Not Necessary	290.00 F	*- F
38	1		*FRT RH UPPER ARM (WCP)	Not Necessary	440.00 F	*- F
39	1		*FRT RH LOWER ARM (WCP)	Bent	440.00 F	*440.00 F
40	1		*CURTAIN AIRBAG RH (WCP)	Broken	950.00 F	*950.00 F
41	1		*FRT SEAT RH AIRBAG (WCP)	Broken	1,300.00 F	*1,300.00 F
42	1		*AIRBAG ECU (WCP)	Necessary	960.00 F	*960.00 F
43	1		*CARPLATE + FRAME	Not Necessary	35.00 FS	*- FS
44	1		*SPOT RIM	Broken	300.00 FS	*300.00 FS
45	1		*FRT RH TYRE (80%)	Torn	150.00 FS	*120.00 FS
46	1		*REAR LH SAFETY BELT (NPA)	Jammed	-	*- F
47	1		*STEERING TIE ROD RH (NPA)	Bent	-	*- F
<u>Supplementary #1</u>						
48	1		*REAR LH SEATBELT (WCP)	Jammed	560.00 F	*560.00 F
49	1		*STEERING TIE ROD RH (WCP)	Bent	220.00 F	*220.00 F
50	1		*RACK END (WCP)	Bent	180.00 F	*180.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	17,090.00	10,745.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,660.50	1,032.50
Total Parts (\$\$)	18,750.50	11,777.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	ALIGNMENT	100.00	80.00
Sub Total (S\$)			100.00	80.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAY PAINT	New	1,100.00	800.00
<u>Labour Items</u>				
2	VEHICLE REPAIR COST	New	2,800.00	900.00
3	CHECK WIRING + CODING	New	1,000.00	200.00
Gross Labour Cost (S\$)			4,900.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >