

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24060220/UQH3M4
Date: 12/07/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003047653		
Claimant Vehicle No :	SMM8765B	Insured Vehicle No :	SML3123S		
Date of Loss:	18/06/2024	Nature of Claim:	TP	Claim No:	364186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM8765B	Engine No:	P520602837
Make & Model:	MAZDA 3, 1.5 4DR M-HYBRID CLASSIC (A)	Chassis No:	JM6BP2SAAK1100055
Reg. Date:	17/07/2019 (Man. Year: 2019)	Odometer:	85394 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,668.00	4,468.10	7,199.90	61.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	1,160.00	2,910.00	71.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,738.00	5,628.10	10,109.90	64.24
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	15,738.00	4,500.00	11,238.00	71.41
+ GST 9.00/9.00% (S\$)	1,416.42	405.00	1,011.42	71.41
Nett Amount (S\$)	17,154.42	4,905.00	12,249.42	71.41

INSPECTION

Date of Assignment:	25/06/2024		
Date Inspected:	25/06/2024	Inspected At:	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2024)
Parts:	143	MAZDA 3 1.5 4DR M-HYBRID CLASSIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM8765B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,125.00 FL	*- FL
2	1		*FRONT BUMPER	Cut/Torn	1,021.00 FL	*995.00 FL
3	1		*FRONT BUMPER SIDE RETAINER N/S	Cracked	65.00 FL	*48.00 FL
4	1		*FRONT BUMPER BEAM	Not Necessary	542.00 FL	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
6	1		*FRONT BUMPER TOP GARNISH	Not Necessary	485.00 FL	*- FL
7	1		*FRONT BUMPER CHROME MOULDING N/S	Scratched	1,011.00 FL	*342.00 FL
8	1		*HEADLAMP N/S	Cracked	3,300.00 FL	*2,266.62 FL
9	1		*HEADLAMP LOWER BRACKET N/S	Cracked	244.00 FL	*89.50 FL
10	1		*FRONT FENDER N/S	Dented/Bent	580.00 FL	*477.00 FL
11	1		*FRONT FENDER INNER SHIELD N/S	Twisted	248.00 FL	*182.00 FL
12	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 FL	*35.00 FL
13	1		*FRONT FENDER INNER SPONGE N/S	Not Necessary	221.00 FL	*- FL
14	1		*FRONT FENDER INNER PANEL N/S	Not Necessary	455.00 FL	*- FL
15	1		*FRONT SHOCK ABSORBER N/S	Not Necessary	580.00 FL	*- FL
16	1		*FRONT LOWER ARM N/S	Not Necessary	788.00 FL	*- FL
17	1		*FRONT KNUCKLE ARM N/S	Not Necessary	745.00 FL	*- FL
18	1		*FRONT KNUCKLE ARM BEARING N/S	Not Necessary	280.00 FL	*- FL
19	1		*FRONT DOOR N/S	Repair	1,215.00 FL	*- FL
20	1		*FRONT SPORT RIM N/S	Cut/Warped	1,580.00 FL	*1,100.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	14,585.00	5,585.12
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,917.00	1,117.02
Total Parts (\$\$)	11,668.00	4,468.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX FRONT PDC SENSOR	New	80.00	0.00
3	TO DISMANTLE & REFIX N/S DOOR MECHANISM	New	120.00	0.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	500.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
6	TO DIAGNOSTIC & REPROGRAMME SYSTEM	New	500.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	480.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
Gross Labour Cost (\$\$)			4,070.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >