



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO JVJ 565

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR FENDER	BROKEN	\$350.00	\$220.00
2	REAR NUMBER PLATE LAMP	BROKEN	\$80.00	\$80.00
1	REAR NUMBER PLATE BRACKET	NOT NECESSARY	\$60.00	\$0.00
2	REAR ABSORBER	BENT	\$800.00	\$700.00
1	TAILLAMP	BROKEN	\$350.00	\$350.00
2	TAILLAMP OUTER COVER	CUT	\$240.00	\$240.00
2	REAR REFLECTOR	NOT NECESSARY	\$80.00	\$0.00
2	REAR FAIRING	CUT	\$600.00	\$500.00
1	EXHAUST SILENCER	NOT NECESSARY	\$650.00	\$0.00
2	EXHAUST SILENCER COVER	CUT	\$180.00	\$180.00
2	FOOTREST BOARD	CUT	\$480.00	\$480.00
2	FOOTREST UNDERCOVER	CUT	\$360.00	\$360.00
1	HANDLE BAR	BENT	\$250.00	\$200.00
1	BRAKE LEVER	BENT	\$90.00	\$90.00
2	WING MIRROR	CUT	\$180.00	\$180.00
1	SET BALANCER	CUT	\$60.00	\$60.00
1	MIDDLE INNER FAIRING	CUT/BROKEN	\$280.00	\$280.00
1	FRONT HEADLAMP	BROKEN	\$680.00	\$680.00
2	FRONT HEADLAMP FAIRING	BROKEN	\$280.00	\$280.00
2	SIDE FAIRING (BLACK)	CUT	\$480.00	\$400.00
1	FRONT HEADLAMP CENTER FAIRING	BROKEN	\$250.00	\$180.00
1	FRONT HEADLAMP INNER FAIRING	NOT NECESSARY	\$250.00	\$0.00
2	FRONT SIGNAL LAMP	BROKEN	\$180.00	\$180.00
1	FRONT FENDER	CUT	\$250.00	\$180.00
2	FRONT FENDER SIDE COVER	CUT	\$180.00	\$150.00
	<b>LESS 10.00% DISCOUNT</b>		(\$764.00)	(\$597.00)
			<b>\$6,876.00</b>	<b>\$5,373.00</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FORK OIL (SN)	NECESSARY	\$30.00	\$30.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FORK SEAL (SN)	NECESSARY	\$30.00	\$30.00
			\$60.00	\$60.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING SYSTEM		\$60.00	\$30.00
	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING		\$800.00	\$400.00
	TO SPRAY FENDER, FAIRINGS AND AFFECTED AREAS		\$800.00	\$300.00
	ALIGNMENT AFTER REPAIR		\$300.00	\$200.00
			\$1,960.00	\$930.00
GRAND TOTAL			\$8,896.00	\$6,363.00
	RECOMMENDED COST OF REPAIR SUM			\$6,000.00
Report Ref No: CS/AGI24100308/Eqp3e2				

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.