

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100309/RQP3E2**Date:** 06/01/2025REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SFT77C**Insured Vehicle No :** SLR9869P

Date of Loss: 13/10/2024

Nature of Claim: TP

Claim No: DMPC2401375H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFT77C**Make & Model: BMW M235I, 3.0 COUPE ABS D/AB 2WD DSC
HID NAV (A)

Engine No: 06579534N55B30A

Reg. Date: 29/11/2016 (Man. Year: 2016)

Chassis No: WBA1J72070V486863

Colour: Blue

Odometer: 126011 km

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R18

Rear Tyre Size: 245/35Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,199.15	5,034.75	164.40	3.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,137.00	8,437.00	1,700.00	16.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,336.15	13,471.75	1,864.40	12.16
+ GST 9.00/9.00% (\$\$)	1,380.25	1,212.46	167.79	12.16
Nett Amount (\$\$)	16,716.40	14,684.21	2,032.19	12.16

INSPECTION

Date of Assignment: 17/10/2024

Date Inspected: 24/10/2024

Inspected At:

Performance Motors Limited (HQ)
303 Alexandra Road, Singapore
Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jan 2025)

Parts: M1-COUPE BMW M235I 3.0 COUPE ABS D/AB 2WD DSC HID NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFT77C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*ALLOY RIM 7.5X18 M DOUBLE SPK 436	Cut	1,139.35 FS	*1,139.35 FS
3	1		*FRONT RH DOOR	Bent	1,479.50 FS	*1,479.50 FS
4	1		*RH SIDE GUIDE FOR BUMPER	Serviceable	164.40 FS	*- FS
5	1		*REAR BUMPER PANEL PRIMED (M)	Cut	1,109.90 FS	*1,109.90 FS
6	1		*FRT RH OUTSIDE DOOR CHANNEL SEALING	Necessary	114.40 FS	*114.40 FS
7	1		*FRT RH DOOR JOINT SEAL	Necessary	87.75 FS	*87.75 FS
8	1		*RH SILL STRIP PRIMED (M)	Deformed	386.20 FS	*386.20 FS
9	1		*RH HOLDING STRIPS SET (M)	Necessary	128.35 FS	*128.35 FS
10	1		*SET MOUNTS PDC SENSOR REAR (M)	Necessary	62.95 FS	*62.95 FS
11	1		*RH SYSTEM LATCH	Cracked	316.15 FS	*316.15 FS
12	1		*(DG/SL) ADHESIVE SET K6	Necessary	60.20 FS	*60.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **5,199.15** **5,034.75**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, FRONT RH DOOR, SIDE SILL RH, ATTACHMENTS AND MAKE GOOD OF REAR RH FENDER	New	5,100.00	3,400.00
2	TO PAINTING REAR BUMPER, REAR RH FENDER, DOOR RH AND SIDE SILL RH	New	3,940.00	3,940.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	177.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	177.00
5	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING. (1X)	New	94.00	94.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATION (1X)	New	531.00	531.00
7	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	118.00
Gross Labour Cost (\$\$)			10,137.00	8,437.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >