

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24100315/ANP3E2
Date: 13/03/2025REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	PC5643G	Insured Vehicle No :	GBH5276Y
Date of Loss:	16/10/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC5643G	Engine No:	1KD2635338
Make & Model:	TOYOTA HARRIER, 3.0 G (MCU30) (A)	Chassis No:	KDH2230029084
Reg. Date:	05/01/2017 (Man. Year: 2016)	Odometer:	478945 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,228.00	7,405.27	6,822.73	47.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	1,790.00	2,340.00	56.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,358.00	9,195.27	9,162.73	49.91
Approved Total (Overridden) (S\$)		7,200.00		
Nett Amount (S\$)	18,358.00	7,200.00	11,158.00	60.78

INSPECTION

Date of Assignment:	17/10/2024	
Date Inspected:	17/10/2024	Inspected At: Automobile Hub Enterprise 1 Kaki Bukit Avenue 6 #01-15 Autobay Singapore 417883
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2025)
Parts:	M1-SUV	TOYOTA HARRIER 3.0 G (MCU30) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5643G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	671.50 FL	*671.50 FL
2	2		*REAR BUMPER SIDE HOLDER	Cracked	116.80 FL	*116.80 FL
3	4		*REAR BUMPER LOWER BRACKET	Bent	96.80 FL	*96.80 FL
4	1		*REAR END PANEL OUTER	Dented	580.40 FL	*580.40 FL
5	1		*REAR END PANEL INNER	Repair	912.70 FL	*- FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	158.60 FL	*158.60 FL
7	2		*REAR END PANEL EXTENSION	Repair	698.20 FL	*- FL
8	2		*TAILLAMP	Cracked	778.80 FL	*778.80 FL
9	2		*TAILLAMP LOWER APRON	Cracked	334.40 FL	*334.40 FL
10	2		*TAILLAMP PANEL	Repair	1,191.00 FL	*- FL
11	1		*TAILGATE	Distorted	1,855.40 FL	*1,855.40 FL
12	1		*TAILGATE LOCK	Jammed	289.90 FL	*289.90 FL
13	1		*TAILGATE LOCK ACTUATOR	Jammed	381.50 FL	*381.50 FL
14	1		*TAILGATE LOCK HANDLE	Not Necessary	110.40 FL	*- FL
15	1		*TAILGATE WEATHERSTRIPE	Cut	329.60 FL	*329.60 FL
16	2		*TAILGATE DAMPER	Not Necessary	351.60 FL	*- FL
17	2		*TAILGATE HINGE	Not Necessary	131.40 FL	*- FL
18	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	364.90 FL	*- FL
19	1		*TAILGATE INNER TRIM BOARD	Not Necessary	481.30 FL	*- FL
20	1		*TAILGATE GLASS	Shattered	1,350.20 FL	*1,350.20 FL
21	1		*TAILGATE GLASS MOULDING	Necessary	198.50 FL	*198.50 FL
22	1		*TAILGATE REAR VIEW MIRROR	Not Necessary	410.90 FL	*- FL
23	1		*TAILGATE WIPER MOTOR	Not Necessary	599.20 FL	*- FL
24	1		*TAILGATE WIPER ARM	Not Necessary	70.40 FL	*- FL
25	1		*TOYOTA LOGO	Necessary	79.10 FL	*79.10 FL
26	1		*HIACE WORDING	Necessary	78.90 FL	*78.90 FL
27	1		*GL WORDING	Necessary	65.50 FL	*65.50 FL
28	1		*SPARE TYRE CARRIER	Bent	285.40 FL	*285.40 FL
29	1		*REAR BODY PANEL LH	Repair	1,822.40 FL	*- FL
30	2		*REAR BODY PANEL INNER TRIM BOARD	Cracked	1,562.40 FL	*1,562.40 FL
31	1		*REAR BODY PANEL AIR VENT LH	Not Necessary	45.90 FL	*- FL
32	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
33	1		*REAR BUMPER REFLECTOR RH	Not Necessary	80.00 FS	*- FS
34	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
35	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
36	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
37	1		*TAILGATE OUTER CHROME MOULDING CLIPS	Not Necessary	20.00 FS	*- FS
38	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
39	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
40	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
41	1		*MALAYSIAN SPEED LIMIT STICKER	Necessary	30.00 FS	*30.00 FS
42	1		*EMERGENCY DOOR STICKER	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
44	1		*REAR VIDEO RECORDER	Not Necessary	580.00 FS	*- FS
45	1		*REAR BODY PANEL INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
46	1		*REAR BODY PANEL GLASS SEALANT	Not Necessary	100.00 FS	*- FS
47	1		*REAR BODY PANEL SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,329.00	9,708.70
- List Item Discount on L Items 25.00/25.00% (\$)	4,101.00	2,303.43
Total Parts (\$)	14,228.00	7,405.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING	New	1,400.00	600.00
3	WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO VACUUM SHATTERED GLASS FRAGMENTS	New	100.00	60.00
9	TO REMOVE REAR BODY PANEL GLASS	New	150.00	0.00
Gross Labour Cost (S\$)			4,130.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >