

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

India International Insurance Pte Ltd  
6 Raffles Quay, #22-00  
Singapore 048580

**Our File No:** CS/III24100318/UQP3M4**Date:** 29/10/2024REFERENCE

Insured/Claimant: YEO PHEK SUAN @ CHENG SOOK CHIN

Policy No: D19MPC0004933

Date of Loss: 17/10/2024

Nature of Claim: OD

Claim No: MPC2024D0012220

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJC3516A**

Make &amp; Model: TOYOTA HARRIER, 2.0 G GRADE (A)

Engine No: 8ARZ094195

Reg. Date: 17/10/2017 (Man. Year: 2017)

Chassis No: JTEKB3GH20J000491

Colour: Silver

Odometer: 160370 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$65,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18

Rear Tyre Size: 235/50R18

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,219.06	4,506.46	712.60	13.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	880.00	770.00	46.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,869.06</b>	<b>5,386.46</b>	<b>1,482.60</b>	<b>21.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,300.00</b>		
<b>- Excess (S\$)</b>	750.00	750.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>6,119.06</b>	<b>3,550.00</b>	<b>2,569.06</b>	<b>41.98</b>

INSPECTION

Date of Assignment: 17/10/2024

Date Inspected: 21/10/2024 Inspected At:

HUP MOTOR TRADING & SERVICE  
BLK 9004 TAMPINES ST 93  
#01-120 SINGAPORE 528838

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 G GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC3516A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S DOOR	Badly Dented	2,870.95 FL	*2,870.95 FL
2	1		*FRONT N/S DOOR LOWER CHROME MOULDING	Cracked	198.27 FL	*198.27 FL
3	1		*FRONT N/S SIDE MIRROR COMP (WITH LIGHTING)	Damaged	2,348.95 FL	*2,348.95 FL
4	1		*FRONT N/S DOOR OUTER CHROME HANDLE	Cut	590.45 FL	*590.45 FL
5	1		*FRONT N/S DOOR LOCK CHROME KNOB	Serviceable	89.16 FL	*- FL
6	1		*FRONT N/S DOOR GLASS OUTER MOULDING	Not Necessary	198.27 FL	*- FL
7	1		*FRONT N/S DOOR GLASS REGULATOR	Serviceable	417.25 FL	*- FL
8	16		*FRONT N/S DOOR TRIM BOARD CLIPS	Not Necessary	68.00 FL	*- FL
9	1		*REAR N/S DOOR LOWER CHROME MOULDING	Not Necessary	177.45 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	6,958.75 6,008.62
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,739.69 1,502.16
					Total Parts (\$\$)	5,219.06 4,506.46

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIX FRONT N/S DOOR GLASS, REGULATOR, INNER LOCK, CHANNEL, WEATHERSTRIPS, TRIM BOARD, CHECKER, HINGE, MOULDING & NECESSARY PARTS	New	150.00	60.00
2	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	650.00	400.00
3	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
4	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	800.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,650.00</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >