Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd

6 Raffles Quay #22-00

Gabriel Wee

Attn:

Singapore 048580

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Date: 18 Oct 2024

Preliminary Advice

Vehicle No: SJC3516AAccident Date: 17/10/2024Make: TOYOTA HARRIERPolicy No.: D19MPC0004933

Assignment Date : 17/10/2024 Excess : \$\\$0.00 Date of Inspection : 21/10/2024 Est. Duration of Repair : 4

Inspection At : HUP MOTOR TRADING & SERVICE

BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,869.06
Revised Amount	:S\$	5,386.46
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,386.46

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 65,000.00

 COE / PARF Rebate
 :S\$ 38,144.00

Salvage Value :S\$

Margin for Repair :S\$ 26,856.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Ki	ndly
	let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: THE VEHICLE REPAIR ON LUMP SUM BASIS.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.