

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 17.10.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLS9501U**
MODEL : **HYUNDAI IONIQ**
DATE OF ACCIDENT : 17.10.2024
TIME OF ACCIDENT : 11:15 HOURS

KMHIC8SICVHU040899
2017
Hui Ray.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dishled</i>	1	\$ 488.00	\$ 488.00
2	REAR BUMPER NUMBER PLATE GARNISH <i>Dishled</i>	1	\$ 108.00 ³²⁸	\$ 108.00 ³²⁸
3	REAR BUMPER NUMBER PLATE LAMP <i>new</i>	2	\$ 86.00	\$ 172.00
4	REAR BUMPER TOWING COVER <i>Dishled</i>	1	\$ 45.00	\$ 45.00
5	REAR BUMPER BRACKET <i>1 piece dish</i>	5	\$ 183.00	\$ 915.00
6	REAR BUMPER REFLECTOR <i>LH ut</i>	2	\$ 96.00	\$ 192.00
7	REAR BUMPER LOWER LIP (CENTER) <i>ut</i>	1	\$ 328.00 ¹⁰⁸	\$ 328.00 ¹⁰⁸
8	REAR BUMPER CENTER LAMP <i>new</i>	1	\$ 288.00	\$ 288.00
9	REAR BUMPER RETAINER <i>new</i>	2	\$ 68.00	\$ 136.00
10	REAR BUMPER REINFORCEMENT <i>crushed</i>	1	\$ 359.00	\$ 359.00
11	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 193.00	\$ 386.00
12	REAR BUMPER BOTTOM INNER GARNISH <i>new</i>	1	\$ 74.00	\$ 74.00
13	REAR BUMPER INNER SIDE GARNISH LH <i>dish</i>	1	\$ 48.00	\$ 48.00
14	TAILGATE <i>Dishled</i>	1	\$ 2,659.00	\$ 2,659.00
15	TAILGATE LAMP <i>new</i>	2	\$ 838.00	\$ 1,676.00
16	TAILGATE REVERSE CAMERA <i>new</i>	1	\$ 988.00	\$ 988.00
17	TAILGATE LOGO	1	\$ 74.00	\$ 74.00
18	TAILGATE EMBLEM 'IONIQ' <i>new</i>	1	\$ 48.00	\$ 48.00
19	TAILGATE EMBLEM 'HYBRID' <i>new</i>	1	\$ 56.00	\$ 56.00
20	TAILGATE DETECTOR <i>crushed</i>	1	\$ 125.00	\$ 125.00
21	TAILGATE DETECTOR WIRE HARNESS <i>new</i>	1	\$ 188.00	\$ 188.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLS9501U**
 MODEL : **HYUNDAI IONIQ**
 DATE OF ACCIDENT : 17.10.2024
 TIME OF ACCIDENT : 11:15 HOURS

22	TAILGATE REVERSEH CAMERA	1	\$ 1,285.00	\$ 1,285.00	X
23	TAILGATE STOPPER	2	\$ 16.00	\$ 32.00	+
24	TAILGATE INNER TRIM	1	\$ 198.00	\$ 198.00	+
25	TAILGATE TOP LOCK	1	\$ 342.00	\$ 342.00	+
26	TAILGATE LOWER LOCK	1	\$ 49.00	\$ 49.00	+
27	TAILGATE WEATHER STRIP	1	\$ 174.00	\$ 174.00	+
28	TAILLAMP <i>left and 2</i>	2	\$ 953.00	\$ 1,906.00	853
29	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 94.00	\$ 94.00	-
30	REAR FENDER COWLING <i>new</i>	2	\$ 109.00	\$ 218.00	+
31	REAR FENDER INNER TRIM <i>new</i>	2	\$ 295.00	\$ 590.00	+
32	REAR END PANEL <i>Dented</i>	1	\$ 552.00	\$ 552.00	-
33	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 81.00	\$ 81.00	-
34	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 399.00	\$ 399.00	-
35	REAR STORAGE BOARD <i>Dented 2 pins</i>	3	\$ 425.00	\$ 1,275.00	850
36	REAR BLIND SPOT SENSOR LH <i>for</i>	1	\$ 1,895.00	\$ 1,895.00	+
37	REAR BLIND SPOT SENSOR WIREHARNESS <i>new</i>	1	\$ 685.00	\$ 685.00	+

7120
5696

TOTAL PRICE \$ 19,128.00
 LESS 20% \$ 3,825.60
SUB TOTAL PRICE \$ 15,302.40

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
3	REAR BUMPER LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
4	REAR BUMPER INNER GRANISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
5	REAR BUMPER BOTTOM INNER GARNISH CLIP <i>new</i>	1	\$ 80.00	\$ 80.00	+
6	TAILGATE SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
8	TAILGATE WINDSCREEN SEALANT <i>green</i>	1	\$ 100.00	\$ 100.00	40
9	TAILGATE WINDSCREEN INNER SHIELD	1	\$ 80.00	\$ 80.00	30
10	TAILGATE BACK GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
11	TAILGATE BACK GLASS INNER SHIELD <i>new</i>	1	\$ 80.00	\$ 80.00	30
12	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	X

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLS9501U**
 MODEL : **HYUNDAI IONIQ**
 DATE OF ACCIDENT : 17.10.2024
 TIME OF ACCIDENT : 11:15 HOURS

13	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
14	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
15	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
16	REAR END PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00

300

TOTAL \$ 1,100.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	700
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	700
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
11	REMOVE AND REFIX TAILGATE WINDSCREEN GLASS	\$ 120.00	80
12	REMOVE AND REFIX TAILGATE BACK GLASS	\$ 100.00	60
13	REMOVE AND REFIX REAR BLIND SPOT SENSOR AND REPROGRAMMING	\$ 650.00	X

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLS9501U**
 MODEL : **HYUNDAI IONIQ**
 DATE OF ACCIDENT : 17.10.2024
 TIME OF ACCIDENT : 11:15 HOURS

14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

1850

TOTAL \$ 5,520.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 16,402.40
 TOTAL LABOUR COST : \$ 5,520.00
 TOTAL REPAIR COST : \$ 21,922.40

Adnan
L/S 18/10/24
06 days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP:8297 9787

total: 7846.
L/S: 6250. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____