



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNF 1359L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILGATE	NOT NECESSARY	\$1,798.00	\$0.00
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	\$212.00	\$0.00
1	TAILGATE LOGO	NOT NECESSARY	\$72.00	\$0.00
1	TAILGATE EMBLEM 'HYBRID'	NOT NECESSARY	\$68.00	\$0.00
1	TAILGATE EMBLEM 'IONIQ'	NOT NECESSARY	\$82.00	\$0.00
1	TAILGATE DETECTOR	NOT NECESSARY	\$211.00	\$0.00
1	TAILGATE WINDSCREEN MOULDING	NOT NECESSARY	\$195.00	\$0.00
2	TAILGATE NUMBER PLATE LAMP @\$68.00	NOT NECESSARY	\$136.00	\$0.00
1	REAR BUMPER	BROKEN	\$987.00	\$459.00
1	REAR BUMPER LOWER	DEFORMED	\$698.00	\$451.00
2	REAR BUMPER SIDE RETAINER @\$68.00	BROKEN	\$136.00	\$136.00
1	REAR BUMPER REINFORCEMENT	BROKEN	\$698.00	\$394.00
1	REAR BUMPER CENTRE LAMP	NOT NECESSARY	\$251.00	\$0.00
1	REAR BUMPER SPONGE	NOT NECESSARY	\$192.00	\$0.00
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	\$112.00	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$678.00	\$0.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	\$312.00	\$0.00
1	NUMBER PLATE LAMP	BROKEN	\$85.30	\$85.30
1	TOW EYE COVER	DEFORMED	\$98.00	\$98.00
	LESS 20.00% DISCOUNT		(\$1,404.26)	(\$324.66)
			\$5,617.04	\$1,298.64

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILGATE STICKER (SN)	NOT NECESSARY	\$100.00	\$0.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	REAR NUMBER PLATE (SN)	BENT	\$50.00	\$40.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR LOWER GLASS SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	\$400.00	\$0.00
1	REVERSE SENSOR (SN)	SHORTED	\$220.00	\$200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
			\$1,300.00	\$270.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING	NOT NECESSARY	\$150.00	\$30.00
	REMOVE AND REFIX REAR LOWER GLASS		\$100.00	\$0.00
	APPLY ANTI RUST ON AFFECTED AREAS		\$100.00	\$20.00
	SPRAY PAINTING ON AFFECTED AREAS		\$800.00	\$400.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$800.00	\$300.00
			\$1,950.00	\$750.00

GRAND TOTAL			\$8,867.04	\$2,318.64
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,850.00
--	---	--	--	-------------------

Report Ref No: CS/INC24100322/Evh3e2				
--------------------------------------	--	--	--	--

TOTAL FOR SPARE PARTS: \$ 6,917.04 \$ 1,568.64
TOTAL FOR LABOUR : \$ 1,950.00 \$ 750.00
TOTAL REPAIR COST: \$ 8,867.04 \$ 2,318.64

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.