



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| | | |
|---|-------|-----------------------|
| MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP) | Ref: | CS/SPF24100325/Kvp3m4 |
| ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) | Date: | 01/11/2024 |
| POLICE LOGISTICS BASE (PLB) | Code: | SPF |
| 1 HEMMANT ROAD SINGAPORE 438675 | | |

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------------------|----------------|------------|
| Insured Veh. | QX 1783P | Veh. Inspected | SKP 1669A |
| Policy No. | - | Coverage | 0 |
| Claim No. | ACS/105/009/2024/056(LK) | Excess | \$0.00 |
| Assign From | LAI PENG CHONG | Assign Date | 18/10/2024 |

2. Vehicle Details

| | | | |
|-----------------|-------------------------------|--------------|----------------|
| Make & Model | TOYOTA HARRIER 2.0 SUV (AUTO) | C.C | 1987 |
| Engine No. | M20A5514392 | Year of Reg. | 24/02/2021 |
| Chassis No. | JTEAC3BH50J000128 | Colour | METALLIC BLACK |
| Odometer | 52753 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: STANDARD ALLOY RIM | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|-----------|-------------|--------------|
| R/H Front Tyre | 225/60R18 | BRIDGESTONE | 9 |
| L/H Front Tyre | 225/60R18 | BRIDGESTONE | 9 |
| R/H Rear Tyre | 225/60R18 | BRIDGESTONE | 9 |
| L/H Rear Tyre | 225/60R18 | BRIDGESTONE | 9 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 11/10/2024 | Inspection Date | 23/10/2024 |
| Survey held at | KBS MOTORSPORTS PTE LTD - 160 SIN MING DRIVE #06-09 SIN MING AUTOCITY, SINGAPORE 575722 | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days