



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 3977B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DENTED	3,468.60	2,265.00
1	FRONT BUMPER LH TOP CORNER	NOT NECESSARY	917.40	-
1	FRONT BUMPER LH COVER	CUT	334.60	334.60
1	LH HEAD LAMP	CRACKED	1,974.60	750.00
1	FRONT TOP GRILLE	CRACKED	2,121.70	2,121.70
1	FRONT LOWER GRILLE	NOT NECESSARY	1,449.20	-
1	HINO LOGO	NECESSARY	320.80	320.80
1	LH SIGNAL LAMP	NOT NECESSARY	350.00	-
	LESS 10% DISCOUNT		-1,093.69	-579.21
			9,843.21	5,212.89
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT "FLAMABLE GAS" STICKER (SN)	NOT NECESSARY	280.00	-
1	SET FRONT COMPANY STICKER (SN)	NOT NECESSARY	800.00	-
			1,080.00	-
<b><u>LABOUR</u></b>				
	TO REMOVE, REFIT, REPLACE DAMAGE LAMPS AND CHECK ELECTRICAL WIRING.		80.00	30.00
	LABOUR CHARGE FOR ANY DISMANTLING OF DAMAGED PARTS AND REPAIR, REALIGNMENT OF BODY STRUCTURE CONSISTENT TO THE ACCIDENT.		1,200.00	400.00
	TO RESPRAY PAINT INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PARTS CONSISTENT TO THE ACCIDENT.		1,200.00	300.00
			2,480.00	730.00
<b>GRAND TOTAL</b>			<b>13,403.21</b>	<b>5,942.89</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,700.00</b>

Report Ref No. CS/AWA24060222/Aqh3m4(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.