



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLE 7096J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	GRAZED	\$741.20	\$701.20
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	\$65.00	\$0.00
1	FRONT FOG LAMP COVER LH	SERVICEABLE	\$180.00	\$0.00
1	FRONT NOZZLE SPRAY COVER LH	TO REPAIR SEE LABOUR	\$75.00	\$0.00
1	FRONT HEADLAMP	SERVICEABLE	\$2,642.60	\$0.00
	LESS 10.00 / 20.00% DISCOUNT		(\$370.38)	(\$140.24)
			\$3,333.42	\$560.96
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NOT NECESSARY	\$30.00	\$0.00
			\$30.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT NOZZLE SPRAY COVER LH		\$550.00	\$150.00
	SPRAY PAINTING		\$500.00	\$220.00
			\$1,050.00	\$370.00
GRAND TOTAL			\$4,413.42	\$930.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$700.00
Report Ref No: CS/AGI24100328/Uqp3e2				

CKS

MARCUS CHUA KANG SENG
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.