



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| | | |
|--|-------|-----------------------|
| MS AUTO & GENERAL INSURANCE (S) PL | Ref: | CS/AGI24100328/Uqp3e2 |
| (BUDGET DIRECT INSURANCE) | Date: | 28/10/2024 |
| 190 CLEMENCEAU AVENUE #03-01 | Code: | AGI |
| SINGAPORE SHOPPING CENTRE SINGAPORE 239924 | | |

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------|----------------|------------|
| Insured Veh. | SLX 3468X | Veh. Inspected | SLE 7096J |
| Policy No. | P10713599R02 | Coverage | 0 |
| Claim No. | C10032266/KC | Excess | \$0.00 |
| Assign From | KIAN CHUAN | Assign Date | 18/10/2024 |

2. Vehicle Details

| | | | |
|-----------------|--------------------|--------------|------------|
| Make & Model | SUBARU OUTBACK (A) | C.C | 2498 |
| Engine No. | FB25Y346677 | Year of Reg. | 29/07/2016 |
| Chassis No. | JF2BS9KC2GG039069 | Colour | WHITE |
| Odometer | 193788 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: SPORTS RIM | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|-----------|----------|--------------|
| R/H Front Tyre | 225/60R18 | YOKOHAMA | 6 |
| L/H Front Tyre | 225/60R18 | YOKOHAMA | 6 |
| R/H Rear Tyre | 225/60R18 | YOKOHAMA | 6 |
| L/H Rear Tyre | 225/60R18 | YOKOHAMA | 6 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 16/10/2024 | Inspection Date | 21/10/2024 |
| Survey held at | FOCUS AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #02-50 KAKI BUKIT @ AUTOBAY SINGAPORE 417883 | | |

| 5a. Remarks |
|---|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |

| 5b. Estimate Days of Repair |
|--|
| ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days |