

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24100333/AUA3Q2

Date: 13/05/2025

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900247920		
Claimant Vehicle No :	SME4578T	Insured Vehicle No :	SMQ4969K		
Date of Loss:	20/10/2024	Nature of Claim:	TP	Claim No:	4633967000SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME4578T	Engine No:	CZE689050
Make & Model:	AUDI Q2 SPORT, 1.4 TFSI COD S-TRONIC (A)	Chassis No:	WAUZZZGA5JA099097
Reg. Date:	28/09/2018 (Man. Year: 2018)	Odometer:	125000 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,801.67	19,908.54	24,893.13	55.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,870.00	2,360.00	5,510.00	70.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,671.67	22,268.54	30,403.13	57.72
Approved Total (Overridden) (S\$)		17,800.00		
(S\$)	52,671.67	17,800.00	34,871.67	66.21
+ GST 9.00/9.00% (S\$)	4,740.45	1,602.00	3,138.45	66.21
Nett Amount (S\$)	57,412.12	19,402.00	38,010.12	66.21
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		20,149.25		
Global Sum Settlement (S\$)		20,150.00		

INSPECTION

Date of Assignment:	21/10/2024	MG Solution Pte Ltd (HQ)
Date Inspected:	21/10/2024 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre
Estimated Period of Repair:	10.0 days	Singapore 415933

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	3,250.00 FL	*- FL
2	1		*FRONT BUMPER LH	Deformed	1,150.30 FL	*1,150.30 FL
3	1		*FRONT BUMPER RH	Deformed	1,150.30 FL	*1,150.30 FL
4	1		*FRONT BUMPER CENTRE OUTER PROTECTOR	Repair	320.00 FL	*- FL
5	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	171.00 FL	*- FL
6	2		*FRONT BUMPER FOGLAMP COVER	Cut	640.00 FL	*640.00 FL
7	1		*FRONT BUMPER TOWING COVER	Cracked	90.00 FL	*90.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Cracked	210.00 FL	*210.00 FL
9	1		*FRONT BUMPER LOWER SPOILER	Deformed	820.00 FL	*820.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	910.00 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	230.00 FL	*230.00 FL
12	1		*FRONT BUMPER REINFORCEMENT COVER	Not Necessary	280.00 FL	*- FL
13	1		*CENTRE GRILLE ASSY	Cracked	1,830.50 FL	*1,830.50 FL
14	1		*HEADLAMP	O/S Cracked	12,500.40 FL	*5,550.00 FL
15	2		*HEADLAMP LOWER BRACKET	Cracked	360.00 FL	*360.00 FL
16	2		*HEADLAMP NOZZLE	Not Necessary	380.00 FL	*- FL
17	2		*HEADLAMP NOZZLE COVER	Not Necessary	180.00 FL	*- FL
18	2		*FRONT FENDER	Not Necessary	1,640.00 FL	*- FL
19	2		*FRONT FENDER ARCH	Not Necessary	640.00 FL	*- FL
20	1		*SUPPORT PANEL	Cracked	1,533.20 FL	*1,164.00 FL
21	2		*SUPPORT PANEL SIDE GUIDE	Not Necessary	190.00 FL	*- FL
22	1		*SUPPORT PANEL TOP COVER	Cracked	210.00 FL	*210.00 FL
23	1		*INTERCOOLER	Not Necessary	1,055.30 FL	*- FL
24	1		*AIRCON CONDENSOR	Not Necessary	920.00 FL	*- FL
25	1		*RADIATOR	Not Necessary	1,177.50 FL	*- FL
26	1		*FAN HOUSING ASSY	Not Necessary	1,785.30 FL	*- FL
27	1		*TAILGATE	Dented	2,955.30 FL	*2,955.30 FL
28	1		*TAILGATE LOGO	Necessary	120.00 FL	*120.00 FL
29	1		*TAILGATE Q2 EMBLEM	Necessary	90.00 FL	*90.00 FL
30	1		*TAILGATE TFSI EMBLEM	Necessary	90.00 FL	*90.00 FL
31	1		*TAILGATE WEATHERSTRIP	Not Necessary	365.00 FL	*- FL
32	1		*TAILGATE LOCK	Damaged	380.00 FL	*380.00 FL
33	1		*TAILGATE ANTENNA SWITCH	Not Necessary	180.00 FL	*- FL
34	1		*TAILGATE INNER TRIM BOARD	Not Necessary	890.00 FL	*- FL
35	1		*TAILGATE WINDSCREEN MOULDING	Necessary	210.00 FL	*210.00 FL
36	1		*REAR BUMPER	Deformed	1,650.20 FL	*1,650.20 FL
37	2		*REAR BUMPER SIDE RETAINER	Not Necessary	185.00 FL	*- FL
38	1		*REAR BUMPER LOWER SPOILER	Deformed	850.00 FL	*850.00 FL
39	1		*REAR BUMPER TOWING COVER	Cut	90.00 FL	*90.00 FL
40	2		*REAR BUMPER REFLECTOR	Not Necessary	300.00 FL	*- FL
41	1		*REAR BUMPER INNER CENTRE FRAME	Cracked	320.00 FL	*320.00 FL
42	1		*REAR BUMPER REINFORCEMENT	Dented	820.00 FL	*820.00 FL
43	2		*REAR BUMPER SENSOR	Damaged	640.00 FL	*640.00 FL
44	4		*REAR BUMPER SENSOR CAP	Necessary	120.00 FL	*120.00 FL
45	2		*REAR BUMPER LOWER BRACKET	Not Necessary	196.00 FL	*- FL
46	2		*REAR TAILLAMP	Not Necessary	3,361.00 FL	*- FL
47	1		*REAR END PANEL OUTER	Not Necessary	520.00 FL	*- FL
48	1		*REAR END PANEL INNER	Not Necessary	980.00 FL	*- FL
49	1		*REAR END PANEL TOP GARNISH	Not Necessary	230.00 FL	*- FL
50	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*50.00 FS
51	1		*SET FRONT BUMPER CLIPS	Necessary	22.00 FS	*22.00 FS
52	1		*SET CENTRE GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
53	1		*REAR NUMBER PLATE	Dented	50.00 FS	*50.00 FS
54	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	20.00 FS	*- FS
55	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
57	1		*REAR BUMPER TOP PROTECTOR (RUBBER)	Necessary	150.00 FS	*120.00 FS
58	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
59	1		*REAR END PANEL INSULATION SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	49,718.30	22,082.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	4,916.63	2,174.06
Total Parts (\$\$)	44,801.67	19,908.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS (FRONT)	New	1,600.00	600.00
2	TO SPRAY PAINT AFFECTED AREA (FRONT)	New	1,600.00	500.00
3	TUFF COAT (FRONT)	New	200.00	0.00
4	WIRING CHECK (FRONT)	New	80.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND TOP UP GAS (FRONT)	New	100.00	60.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST (FRONT)	New	100.00	60.00
7	PANEL BEATING ,REMOVAL AND REPLACING PARTS (REAR)	New	1,600.00	400.00
8	TO SPRAY PAINT AFFECTED AREA (REAR)	New	1,600.00	400.00
9	TUFF COAT (REAR)	New	200.00	0.00
10	WIRING CHECK (REAR)	New	80.00	30.00
11	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR (REAR)	New	250.00	0.00
12	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING (REAR)	New	100.00	50.00
13	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING (REAR)	New	100.00	50.00
14	REMOVE AND REFIX REAR WINDSCREEN (REAR)	New	140.00	120.00
15	TRANSFER BOOTLID MECHANISM (REAR)	New	120.00	60.00
Gross Labour Cost (\$\$)			7,870.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >