

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24100334/UQP3E2
Date: 07/11/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003313722
Claimant Vehicle No :	SJK8565H	Insured Vehicle No :	SNP3456Z
Date of Loss:	17/10/2024	Nature of Claim:	TP
		Claim No:	377095

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK8565H	Engine No:	27195031036098
Make & Model:	MERCEDES-BENZ C200 KOMPRESSION, 1.8 (A)	Chassis No:	WDD2040412A131264
Reg. Date:	06/11/2008 (Man. Year: 2008)	Odometer:	74379 km
Colour:	Blue		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Matrax 6 mm	Rear Left Side:	Matrax 6 mm
Front Right Side:	Matrax 6 mm	Rear Right Side:	Matrax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,533.78	3,639.46	9,894.32	73.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	620.00	1,110.00	64.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,263.78	4,259.46	11,004.32	72.09
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	15,263.78	3,400.00	11,863.78	77.73
+ GST 9.00/9.00% (S\$)	1,373.74	306.00	1,067.74	77.73
Nett Amount (S\$)	16,637.52	3,706.00	12,931.52	77.73

INSPECTION

Date of Assignment:	21/10/2024	
Date Inspected:	21/10/2024	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2024)
Parts:	143	MERCEDES-BENZ C200 KOMPRESSOR 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK8565H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	2,115.32 F	*1,512.32 FL
2	1		*FRONT BUMPER BEAM	Serviceable	945.10 F	*- FL
3	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Cut / Twisted	324.00 F	*166.00 FL
4	1		*FRONT BUMPER FOG LAMP O/S	Cracked	450.00 F	*345.20 FL
5	1		*SET FRONT BUMPER CLIPS & RIVET	Necessary	60.00 F	*60.00 FL
6	1		*FRONT BUMPER LOGO	Not Necessary	85.00 F	*- FL
7	1		*FRONT BUMPER SPONGE	Torn	162.00 F	*162.00 FL
8	1		*FRONT BUMPER INNER TOP RETAINER	Not Necessary	322.00 F	*- FL
9	1		*SET FRONT BUMPER CHROME MOULDING	Necessary / Cracked	232.00 F	*232.00 FL
10	1		*FRONT HEADLAMP O/S	Holder Cracked	3,500.00 F	*1,566.32 FL
11	1		*FRONT SUPPORT PANEL	Repair	1,045.11 F	*- FL
12	1		*FRONT LICENCE PLATE	Not Necessary	50.00 F	*- FL
13	1		*FRONT GRILLE ASSY	Not Necessary	1,012.00 F	*- FL
14	1		*FRONT GRILLE LOGO	Not Necessary	420.00 F	*- FL
15	1		*BONNET	Not Necessary	2,111.25 F	*- FL
16	2		*BONNET HINGES	Not Necessary	700.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	13,533.78	4,043.84
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	404.38
Total Parts (\$\$)	13,533.78	3,639.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	0.00
3	TO REFILL AIR CON GAS	New	120.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	680.00	300.00
5	TO PUTTY & SPRAY PAINTING	New	800.00	300.00
Gross Labour Cost (S\$)			1,730.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >