

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100339/RUA3Q2
Date: 16/05/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0003685_01
Claimant Vehicle No : SCH6818R Insured Vehicle No : SMS2730J
Date of Loss: 15/10/2024 Nature of Claim: TP Claim No: MFL2024D0012398

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCH6818R
Make & Model: MASERATI LEVANTE, 3.0 GRANSPORT (A) Engine No: 403522
Reg. Date: 01/04/2019 (Man. Year: 2018) Chassis No: ZN6YU61C00X292138
Colour: Blue Odometer: 54187 km
Engine Capacity: 2979 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/45 R20 Rear Tyre Size: 265/45 R20
Front Left Side: Scorpion 7 mm Rear Left Side: Scorpion 7 mm
Front Right Side: Scorpion 7 mm Rear Right Side: Scorpion 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	84,850.56	64,650.22	20,200.34	23.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	34,980.00	18,230.00	16,750.00	47.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	119,830.56	82,880.22	36,950.34	30.84
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 21/10/2024
Date Inspected: 21/10/2024 Inspected At: Tridente Automobili Pte Ltd (HQ)
30 Leng Kee Road #01-02
Singapore 159100
Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2025)
Parts:	143	MASERATI LEVANTE 3.0 GRANSPORT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCH6818R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY AND MISCITEM	Necessary	150.00 FS	*75.00 FS
2	1		*BONNET	Bent	8,332.96 FS	*8,332.96 FS
3	4		*PAD NOISE VIBRATION	Not Necessary	245.20 FS	*- FS
4	1		*FRONT LID SH HINGE	Bent	637.89 FS	*637.89 FS
5	1		*FRONT LID RH HINGE	Bent	637.89 FS	*637.89 FS
6	1		*PLUG	Not Necessary	29.98 FS	*- FS
7	2		*GAS SPRING	Not Necessary	266.80 FS	*- FS
8	1		*PPG LABEL BLU EM VR-406/C666	Necessary	38.10 FS	*38.10 FS
9	1		*A/C SYSTEM COOLANT LABEL	Not Necessary	20.20 FS	*- FS
10	1		*FRONT BUMPER M161	Cracked	6,645.94 FS	*6,645.94 FS
11	1		*RADIATOR GRILLE	*Check	4,145.50 FS	*- FS
12	1		*FRONT SKID PLATE BLACK (4UV+)	Scratched	1,467.60 FS	*1,467.60 FS
13	1		*LOWER CENTRAL FRONT BUMPER S	Deformed	6,282.50 FS	*6,282.50 FS
14	1		*LH BRACKET	Scratched	29.50 FS	*29.50 FS
15	1		*RH BRACKET	Scratched	29.50 FS	*29.50 FS
16	1		*RH TOP FRONT GRILLE BUMPER	*Check	431.80 FS	*- FS
17	1		*LH TOP FRONT GRILLE BUMPER	*Check	431.80 FS	*- FS
18	8		*RIVET	Necessary	118.16 FS	*118.16 FS
19	1		*AIR DUCT	*Check	508.10 FS	*- FS
20	1		*CENTRAL TOP FRONT GRILLE BUM	*Check	354.80 FS	*- FS
21	1		*LOWER GRILLE FOR PARKING SEN	*Check	427.20 FS	*- FS
22	1		*FRONT TOW HOOK PLUG	Not Necessary	15.10 FS	*- FS
23	2		*FOG LAMP FRAME CHROME	*Check	253.60 FS	*- FS
24	1		*FRONT BUMPER ABSORBER	Cracked	300.10 FS	*300.10 FS
25	12		*FIXING BUTTON	Necessary	192.60 FS	*192.60 FS
26	1		*FRONT BUMPER ADHESIVE M161	Necessary	33.52 FS	*33.52 FS
27	1		*AIR SHUTTER	Scratched	2,899.85 FS	*2,899.85 FS
28	6		*SILICON RING	Necessary	262.80 FS	*262.80 FS
29	2		*PARKING SENSOR	*Check	659.90 FS	*- FS
30	4		*RADIAL PARKING SENSOR	*Check	2,708.80 FS	*- FS
31	1		*FRONT SENSOR HOUSING	*Check	15.10 FS	*- FS
32	1		*FRONT SENSOR HOUSING	*Check	15.10 FS	*- FS
33	1		*FRONT SENSOR HOUSING	*Check	15.10 FS	*- FS
34	1		*FRONT SENSOR HOUSING	*Check	15.10 FS	*- FS
35	1		*FRONT BUMPER WIRING HARNESS	*Check	574.40 FS	*- FS
36	1		*CPL LH FRONT FENDER	Bent	3,643.10 FS	*3,643.10 FS
37	1		*LH MUDGUARD SUPPORT BRACKET	*Check	89.88 FS	*- FS
38	1		*LH MUDGUARD FRONT LOWER REIN	*Check	116.85 FS	*- FS
39	6		*RIVET	Necessary	73.32 FS	*73.32 FS
40	3		*LH FENDER AIR VENT	Necessary	1,411.80 FS	*1,411.80 FS
41	1		*LH GRANSPORT LATERAL EMBLEM	Necessary	313.85 FS	*313.85 FS
42	1		*EMBLEM M161	Necessary	351.98 FS	*351.98 FS
43	1		*BLOCK	Not Necessary	13.02 FS	*- FS
44	1		*BRACKET	Necessary	89.80 FS	*89.80 FS
45	1		*RIVET	Necessary	16.94 FS	*16.94 FS
46	1		*HEX FLANGE SCREW M8X35	Not Necessary	16.94 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*FRONT FOG LAMP	Not Necessary	5,300.60 FS	*- FS
48	1		*RH HEADLIGHT	Cracked	9,421.20 FS	*9,421.20 FS
49	1		*LH HEADLIGHT	Cracked	9,421.20 FS	*9,421.20 FS
50	2		*RIVET	Necessary	27.06 FS	*27.06 FS
51	1		*RH SIDE AIR DUCT	Cracked	537.88 FS	*537.88 FS
52	1		*LH SIDE AIR DUCT	Not Necessary	537.88 FS	*- FS
53	1		*FRONT CROSS MEMBER ASS	Cracked	3,429.50 FS	*3,429.50 FS
54	8		*SCREW AND WASHER	Necessary	110.88 FS	*110.88 FS
55	1		*THIRD LOAD PATH CROSS MEMBER	Scratched	1,312.58 FS	*1,312.58 FS
56	2		*RIVET	Necessary	33.88 FS	*33.88 FS
57	2		*BRACKET	Necessary	51.80 FS	*51.80 FS
58	4		*WASHER	Necessary	44.00 FS	*44.00 FS
59	4		*SPECIAL SCREW	Necessary	115.48 FS	*115.48 FS
60	4		*SCREW	Necessary	39.52 FS	*39.52 FS
61	1		*RH INTERCOOLER	*Check	2,484.02 FS	*- FS
62	1		*RH INTERCOOLER BRACKET	*Check	180.74 FS	*- FS
63	1		*RH LOWER INTERCOOLER BRACKET	*Check	105.73 FS	*- FS
64	2		*COLLAR	*Check	84.50 FS	*- FS
65	4		*SCREW	*Check	61.60 FS	*- FS
66	1		*LH FRONT WHEEL ARCH (PRIMERI)	Cracked	2,787.34 FS	*2,787.34 FS
67	1		*RH FRONT WHEEL ARCH (PRIMERI)	Cracked	2,787.34 FS	*2,787.34 FS
68	18		*PIN	Necessary	400.14 FS	*400.14 FS
69	4		*WHEELHOUSE LINER ADHESIVE BU	Necessary	57.12 FS	*57.12 FS
70	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
71	10		*ADHESIVE TAPE	Necessary	138.60 FS	*138.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	84,850.56	64,650.22
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE DAMAGED BODY PARTS AND REPLACE EFFECTE	New	18,720.00	8,250.00
2	TO SPRAY PANEL PAINT ON FRONT INNER & OUTTER PA	New	13,500.00	8,000.00
3	TO CHECK AND CLEAR FAULT AFTER ACCIDENT REPAIR	New	1,200.00	1,200.00
4	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FU	New	780.00	390.00
5	LABOUR TO PERFORM HEADLIGHT ADAPTION	New	780.00	390.00
Gross Labour Cost (\$\$)			34,980.00	18,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >