

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No.

19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	SOMPO INSURANC	CE SINGAPORE PL	Ref:	CS3/SMO24100343/Uqp3e2
	50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623		Date:	28/10/2024
	SINGAPORE LAND	TOWER SINGAPORE 040023	Code:	SMO
1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	FBP 5072B	Veh. Inspected	SMF 4715J
	Policy No.	D21MTMCO1005167	Coverage	0
	Claim No.	CMTD2403327/GPL	Excess	\$0.00
	Assign From	GNOH PAU LOONG	Assign Date	21/10/2024
2. Vehicle Details				
	Make & Model	KIA CERATO (A)	C.C	1591
	Engine No.	G4FGJH709097	Year of Reg.	13/11/2018
	Chassis No.	KNAF3416MK5018323	Colour	RED
	Odometer	87474 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	205/55R16	YOKOHAMA	6
	L/H Front Tyre	205/55R16	YOKOHAMA	6
	R/H Rear Tyre	205/55R16	YOKOHAMA	6
	L/H Rear Tyre	205/55R16	YOKOHAMA	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5.	General Information			
	Accident Date	11/10/2024	Inspection Date	
	3. Survey held at 1, KAKI BUKIT AVE 6 #02-38, AUTOBAY @ KAKI BUKIT SINGAPORE 417883 - REPAIRER: SKS AUTOMOBILE SOLUTION			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000				
5b. Estimate Days of Repair				

CKS

MARCUS CHUA KANG SENG Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days